



U.S. Post Office, Spokane, Washington

Photographer: Kristine Bak

Date of Photograph: 8/80

Location of Negative: GSA Center, Auburn, WA

Front Facade looking NW from Lincoln and
Riverside.

Photograph #1 of 4



U.S. Post Office, Spokane, Washington

Photographer: Kristine Bak

Date of Photograph: 8/80

Location of Negative: GSA Center, Auburn, WA

East Facade looking NW from Lincoln and

Riverside.

Photograph #2 of 4



U.S. Post Office, Spokane, Washington

Photographer: Kristine Bak

Date of Photograph: 8/80

Location of Negative: GSA Center, Auburn, WA

Rear Facade looking SE from Main.

Photograph #3 of 4



U.S. Post Office, Spokane, Washington

Photographer: Kristine Bak

Date of Photograph: 8/80

Location of Negative: GSA Center, Auburn, WA

West Facade looking SE from Main

Photograph #4 of 4



SERVICE INFORMATION CENTER

General Services Administration



STAMP COLLECTING

PLEASE ENTER HERE


U.S. Post Office, Spokane, Washington

Photographer: Kristine Bak

Date of Photograph: 8/80

Location of Negative: GSA Center, Auburn, WA
East Lobby looking North.

Photograph #4 of 15



U.S. Post Office, Spokane, Washington

Photographer: Kristine Bak

Date of Photograph: 8/80

Location of Negative: GSA Center, Auburn, WA

Detail of Central Entrance on Riverside.

Photograph #1 of 15



U.S. Post Office, Spokane, Washington


Photographer: Kristine Bak

Date of Photograph: 8/80

Location of Negative: GSA Center, Auburn, WA

Head Detail of SE Entrance on Riverside.

Photograph #2 of 15



U.S. Post Office, Spokane, Washington

Photographer: Kristine Bak

Date of Photograph: 8/80

Location of Photograph: GSA Center, Auburn, WA
First Floor Toilet Room Window East of Main
Entrance.

Photograph #3 of 15



U.S. Post Office, Spokane, Washington

Photographer: Kristine Bak

Date of Photograph: 8/80

Location of Negative: GSA Center, Auburn, WA
East Lobby looking South

Photograph #5 of 15



U.S. Post Office, Spokane, Washington

Photographer: Kristine Bak

Date of Photograph: 8/80

Location of Negative: GSA Center, Auburn, WA

First Floor East Lobby Plaster Capital.

Photograph #6 of 15



U.S. Post Office, Spokane, Washington

Photographer: Kristine Bak

Date of Photograph: 8/80

Location of Negative: GSA Center, Auburn, WA

Main Stairway First Floor East Lobby

Photograph #8 of 15

FEDERAL BUILDING 222 POST OFFICE
 SPOKANE, WASHINGTON
 NO SOLICITING

IN BARRINGTON COURT	214
JUDGE L. MARION HANEY	
CLERK	212
CLERK J. S. MCNEELY	212
IN COURTHOUSE	212
BRIDGE FIELD ENG CORP DEPT OF ENERGY CONTRACTOR 242	
DISASTER FIELD OFFICE 201	
US DEPT OF ENERGY - GRANTING RESOURCES 230	
WAGE SURVEY PLAN TRUSTEE - P.R. 202 242	
US POSTAL SERVICE	
POSTMASTER	221
CUSTOMER SERVICE REPRESENTATIVE	222
HANDICAP CUSTOMER SERVICE	222
POST OFFICE PERSONNEL	222
MAILING UNIT/MAIL SERVICE	222
SAFETY ASSISTANT	222

224

NO SOLICITING
 NO LOBBYING
 NO SIGNING

U.S. Post Office, Spokane, Washington

Photographer: Kristine Bak

Date of Photograph: 8/80

Location of Negative: GSA Center, Auburn, WA

Elevator Lobby looking NE.

Photograph #7 of 15



U.S. Post Office, Spokane, Washington

Photographer: Kristine Bak

Date of Photograph: 8/80

Location of Negative: GSA Center, Auburn, WA
Courtroom Vestibule looking West third floor

Photograph #10 of 15



U.S. Post Office, Spokane, Washington

Photographer: Kristine Bak

Date of Photograph: 8/80

Location of Negative: GSA Center, Auburn, WA
Brass Finial NE Stairway.

Photograph #9 of 15



U.S. Post Office, Spokane, Washington

Photographer: Kristine Bak

Date of Photograph: 8/80

Location of Negative: GSA Center, Auburn, WA

Marble Balustrade along Courtroom Vestibule
looking NE third floor.

Photograph #11 of 15



U.S. Post Office, Spokane, Washington

Photogrpaer: Kristine Bak

Date of Photograph: 8/80

Location of Negative: GSA Center, Auburn, WA

Original light fixture third floor Court-
room Vestibule.

Photograph #12 of 15



U.S. Post Office, Spokane, Washington

Photographer: Kristine Bak

Date of Photograph: 8/80

Location of Negative: GSA Center, Auburn, WA

Third floor Courtroom looking NW.

Photograph #13 of 15



U.S. Post Office, Spokane, Washington

Photographer: Kristine Bak

Date of Photograph: 8/80

Location of Negative: GSA Center, Auburn, WA

Third floor Courtroom looking SW

Photograph #14 of 15



U.S. Post Office, Spokane, Washington

Photographer: Kristine Bak

Date of Photograph: 8/80

Location of Negative: GSA Center, Auburn, WA
Plaster Cornice SE Corner third floor Court-
room.

Photograph #15 of 15