



Robert Mills DAIRY BARN, HALF MOON BAY, CA 94019

UNKNOWN, CA 1925

CALIFORNIA STATE PARKS, SAN MATEO DIST. 95 KELLY AVE.
HALF MOON BAY, CA. 94019

Looking north with Mills Creek and stone retaining wall in foreground. First building on right was grain mill, second building with side shed was blacksmith shop and milk house (both no longer extant). Mills DAIRY BARN ON LEFT with "red grainery" to rear (only root cellar now exists). Note wheat field on hill MASS to rear.



ROBERT MILLS DAIRY BANK, HALF MOON BAY, CA 94019

KENT L. SEAVEY, 1989

CALIFORNIA STATE PARKS, SAN MATEO DIST., 95 KELLY AVE,
HALF MOON BAY, CA 94019

LOOKING GENERALLY NORTH WITH MILLS DAIRY BANK
ON LEFT (SOUTH END ELEVATION). NOTE VEGETATION
ALONG MILLS CREEK TO RIGHT.



ROBERT MILLS DAIRY BARN, HALF MOON BAY, CA 94019

KENT L. SLAVEY, 1989

CALIFORNIA STATE PARKS, SHUMATELLO DIST. 95 KELLY AVE.

HALF MOON BAY, CA 94019

LOOKING NORTH WEST AT SIDE ELEVATION (EAST) OF MILLS
DAIRY BARN.




ROBERT MILLS DAIRY BARN, HALF MOON BAY, CA 94019

KENT L. SEAVEY, 1989.

CALIFORNIA STATE PARKS, SAN MATEO DIST. 95 KELLY AVE.
HALF MOON BAY, CA 94019

Looking south east AT uphill side ELEVATION (west)
of MILLS DAIRY BARN, NOTE Loading BAYS AND
TWO ROOF DORMERS.



ROBERT MILLS DAIRY BARN, HALF MOON BAY, CA
KENT L. SEAVEY, 1989

CALIFORNIA STATE PARKS, SAN MATEO DIST.
95 KELLY AVE. HALF MOON BAY, CA 94019

Looking EAST AT THE NORTH END ELEVATION
OF THE ROBERT MILLS DAIRY BARN, NOTE
RAIL FOR SLIDING DOOR (NO LONGER EXTANT)



ROBERT MILLS DAIRY BARN, HALF MOON BAY, CA 94017

KENT L. SEAVEY, 1989

CALIFORNIA STATE PARKS, SAN MATEO DIST. 95 KELLY AVE.
HALF MOON BAY, CA 94017

Looking west toward foundation work (stone) of
MASTERMASON G. B. MARTINI. Note horizontal line in wall
ABOUT HALF WAY UP WALL SUGGESTING UPPER PARTS MAY
HAVE BEEN INFILLED BEHIND FOR ROADBED.



ROBERT MILLS DAIRY BARN, HALF MOON BAY, CA 94019

KENT L. SEAVEY, 1989

CALIFORNIA STATE PARKS, SAN MATEO DIST, 95 KELLY AVE
HALF MOON BAY, CA 94019

LOOKING SOUTHWEST - AT THE FORMER CATTLE STALLS
BUILT INTO THE BUTTRESSES OF THE STONE RETAINING
WALL. NOTE HEAVY BEAMS ON TOP OF BUTTRESSES
SUPPORTING FLOOR JOISTS.



Robert Mills DAIRY BARN, HALF MOON BAY CA 94019
KENT L. SEAVEY, 1989

CALIFORNIA STATE PARLSS, SANMATEO DIST. 95 KELLY AVE.
HALF MOON BAY, CA 94019

LOOKING SOUTHEAST AT THE CATILE TROUGHs AND STRUCTURAL
SUPPORTS OF THE MILLS DAIRY BARN. DROP BOXES ARE
LOCATED ABOVE WHERE HAY AND OTHER FEED WAS DROPPED
THROUGH FROM THE LOFT.



ROBERT MILLS DAIRY BARN
HALF MOON BAY, CA 94019

KENT L. SEAVEY, 1989

CALIFORNIA STATE PARKS, SAN MATEO DIST
75 KELLY AVE. HALF MOON BAY CA 94019

LOOKING GENERALLY SOUTH ALONG
THE INTERIOR OF THE MILLS DAIRY BARN
LOFT. NOTE THE SYSTEM OF VERTICAL
IRON RODS HOLDING THE STRUCTURE IN
TENSION.



ROBERT MILLS DAIRY BARN HALF MOON BAY, CA 94019
KENT L. SEAVEY, 1989.

CALIFORNIA STATE PARKS, SAN MATEO DIST., 95 KELLY AVE.
HALT MOON BAY, CA 94019

LOOKING SOUTHEAST TOWARD A FORMER MILLS DAIRY
RESIDENCE ABOUT 100 YARDS EAST OF THE MILLS DAIRY
BARN.