

Photographer: Clifford M. Renshaw Date: February, 1987 Negative filed at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, RI 02903

View: Front elevation (West) on America Street.


Photo #2

MAY 1 9 1987



Photographer: Clifford M. Renshaw Date: February, 1987 Negative filed at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, RI 02903

View: Rear and side elevations (East and North).



Photographer: Clifford M. Renshaw Date: February, 1987 Negative filed at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, RI 02903

View: Main entrance on the West elevation; a recessed doorway within the center of three, equal sized arch arches. A terra cotta stringcourse abuts the keystone of this arcade and terra cotta roundels are within the spandrels.



Photographer: Clifford M. Renshaw Date: February, 1987 Negative filed at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, RI 02903

View: Side elevation ((North).



Photographer: Clifford M. Renshaw Date: February, 1987 Negative filed at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, RI 02903

View: Side entrance on the South elevation which is identical to the North, side elevation. There are double doors framed by squat pilaster strips and capped by a vaguely Ionic entablature.



Photographer: Clifford M. Renshaw Date: February, 1987 Negatives filed at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, RII02903

View: Multi-Light, half-round fanlights in the Principal's room adjacent to the main entrance; identical detail in the teachers' room on the other of the entrance.



Photographer: Clifford M. Renshaw Date: February, 1987 Negatives filed at: Rhode Išland Historical Preservation Commission 150 Benefit Street Providence, Rhode Island 02903

View: Stairwell on the North end of the building which is identical to the South stairwell. Oak and glass partitions separate the stairhalls from the central corridor.



Photographer: Clifford M. Renshaw Date: February, 1987 Negatives filed at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, RI 02903

View: Detail of the oak and glass partition separating the stairhall and corridor at the north end of the huithenbuilding.



Photographer: Clifford M. Renshaw Date: February, 1987 Negatives filed at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, RI 02903

View: Typical interior wall elevation at the front of the classroom. View off the east wall of the the second floor, Southwest classroom.

Photo #10

MAY 1 9 1987