

SURVEY FORM FOR 1930'S RESIDENCES (12)

ADDRESS: 1102 - East Kansas

13/392125/5318370

DESCRIPTION: Type P-2

SIDING: Wood _____ Asbestos _____ Metal X Green
White stucco entrance, red brock fireplace
Brick _____ ~~XXXXXX~~ _____

DATE SIDING ADDED (if known): fall, 1980.

DATE GARAGE BUILT (if known): summer, 1934 (original)

STORM WINDOWS: Wood Frame _____ Aluminum Frame X.

STORM DOORS: Wood Frame _____ Aluminum Frame X.

CHANGE IN DOOR LOCATION: Yes _____ No X

CHANGE IN WINDOW LOCATION: Yes _____ No X

ORIGINAL PAINT SCHEME: Yes _____ No X

CHANGE IN PORCH STRUCTURE: Yes X No _____

AGE OF HOUSE (in years): 51 years

INTERIOR AND STRUCTURAL CHANGES (Fill in as necessary for each house): (briefly)

Interior - repainted October 1980

Metal siding placed over (8" x 3/4" wood) - fall 1980

Changed to combination storm windows - summer 1976

Changed to combination storm doors - summer 1973

Added 4' plywood lower outside wall of porch and rescreened upper - summer 1981

FORM COMPLETED BY: Norris A. Forum

DATE: 18 Jan 82



SURVEY FORM FOR 1930'S RESIDENCES (12)

ADDRESS: 1103 - East Kansas

13/392120/5318405

DESCRIPTION: Type P-4

SIDING: Wood _____ Asbestos _____ Metal X Brown - porch
Yellow
Entrance - native stone, red brick fireplace
Brick _____ Stone X

DATE SIDING ADDED (if known): fall, 1980.

DATE GARAGE BUILT (if known): summer, 1934 (original)

STORM WINDOWS: Wood Frame _____ Aluminum Frame X.

STORM DOORS: Wood Frame _____ Aluminum Frame X.

CHANGE IN DOOR LOCATION: Yes _____ No X

CHANGE IN WINDOW LOCATION: Yes _____ No X

ORIGINAL PAINT SCHEME: Yes _____ No X

CHANGE IN PORCH STRUCTURE: Yes X No _____

AGE OF HOUSE (in years): 51 years

INTERIOR AND STRUCTURAL CHANGES (Fill in as necessary for each house): (briefly)

Added 1/2 bathroom and bedroom in basement (date unknown)

Interior - repainted July 1973

Metal siding placed over (8" x 3/4" wood) - fall 1980 -

Changed to combination storm windows summer 1976

Changed to combination storm doors summer 1973

Added 4' plywood lower outside wall of porch and rescreened upper - summer 1981

FORM COMPLETED BY: Norris A. Forum

DATE: 18 Jan 82



SURVEY FORM FOR 1930'S RESIDENCES (12)

ADDRESS: 1104 - East Kansas

13/392120/5318440

DESCRIPTION: Type P-2

Outside - Dove gray

Shakes
SIDING: Wood Asbestos _____ Metal _____
Brick _____ Stone _____ Red brick fireplace

DATE SIDING ADDED (if known): Summer, 1934 (original)

DATE GARAGE BUILT (if known): Summer, 1934 (original)

STORM WINDOWS: Wood Frame _____ Aluminum Frame

STORM DOORS: Wood Frame _____ Aluminum Frame

CHANGE IN DOOR LOCATION: Yes _____ No

CHANGE IN WINDOW LOCATION: Yes _____ No

Outside - dove gray
ORIGINAL PAINT SCHEME: Yes No _____

CHANGE IN PORCH STRUCTURE: Yes No _____

AGE OF HOUSE (in years): 51 years

INTERIOR AND STRUCTURAL CHANGES (Fill in as necessary for each house): (briefly)

Interior - repainted August 1979

Changed to combination storm windows - summer 1976

Changed to combination storm doors - summer 1973

Added 4' plywood lower outside wall of porch and rescreened upper - summer 1981

FORM COMPLETED BY: Norris A. Forum

DATE: 18 Jan 82



SURVEY FORM FOR 1930'S RESIDENCES (12)

ADDRESS: 1105 - East Kansas

13/392115/5318470

DESCRIPTION: Type P-4

SIDING: Wood _____ Asbestos _____ Metal X Brown - porch
Yellow
Brick _____ White stucco entrance,
~~Stone~~ _____ red brick fireplace

DATE SIDING ADDED (if known): September, 1980.

DATE GARAGE BUILT (if known): Summer, 1934 (original)

STORM WINDOWS: Wood Frame _____ Aluminum Frame X.

STORM DOORS: Wood Frame _____ Aluminum Frame X.

CHANGE IN DOOR LOCATION: Yes _____ No X

CHANGE IN WINDOW LOCATION: Yes _____ No X

ORIGINAL PAINT SCHEME: Yes _____ No X

CHANGE IN PORCH STRUCTURE: Yes X No _____

AGE OF HOUSE (in years): 51 years

INTERIOR AND STRUCTURAL CHANGES (Fill in as necessary for each house): (briefly)

Added 1/2 bathroom and two bedrooms in basement (date unknown)

Interior - repainted April 1979

Metal siding placed over (8" x 3/4" wood) - fall 1980

Changed to combination storm windows - summer 1976

Changed to combination storm doors - summer 1973

Added 4' plywood lower outside wall of porch and rescreened upper - summer 1981

FORM COMPLETED BY: Norris A. Forum

DATE: 18 Jan 82



SURVEY FORM FOR 1930'S RESIDENCES (12)

ADDRESS: 1106 - East Kansas

13/392110/5318500

DESCRIPTION: Type P-3

Outside - Dove gray

Shakes

SIDING: Wood Asbestos _____ Metal _____
Red brick fireplace
Brick _____ Stone _____

DATE SIDING ADDED (if known): Summer, 1934 (original)

DATE GARAGE BUILT (if known): Summer, 1934 (original)

STORM WINDOWS: Wood Frame _____ Aluminum Frame .

STORM DOORS: Wood Frame _____ Aluminum Frame .

CHANGE IN DOOR LOCATION: Yes _____ No

CHANGE IN WINDOW LOCATION: Yes _____ No

ORIGINAL PAINT SCHEME: Yes No _____

CHANGE IN PORCH STRUCTURE: Yes No _____

AGE OF HOUSE (in years): 51 years

INTERIOR AND STRUCTURAL CHANGES (Fill in as necessary for each house): (briefly).

Added 1/2 bathroom and one bedroom (date unknown)

Interior - repainted December 1980

Changed to combination storm windows - summer 1976

Changed to combination storm doors - summer 1973

Added 4' plywood lower outside wall of porch and rescreened upper - summer 1981

FORM COMPLETED BY: Norris A. Forum

DATE: 18 Jan 82



SURVEY FORM FOR 1930'S RESIDENCES (12)

ADDRESS: 1107 - East Kansas

13/392100/5318530

DESCRIPTION: Type P-2

SIDING: Wood _____ Asbestos _____ Metal X Blue
Red brick entrance and fireplace
Brick X Stone _____

DATE SIDING ADDED (if known): fall, 1980.

DATE GARAGE BUILT (if known): summer, 1934 (original)

STORM WINDOWS: Wood Frame _____ Aluminum Frame X.

STORM DOORS: Wood Frame _____ Aluminum Frame X.

CHANGE IN DOOR LOCATION: Yes _____ No X

CHANGE IN WINDOW LOCATION: Yes _____ No X

ORIGINAL PAINT SCHEME: Yes _____ No X

CHANGE IN PORCH STRUCTURE: Yes X No _____

AGE OF HOUSE (in years): 51 years

INTERIOR AND STRUCTURAL CHANGES (Fill in as necessary for each house): (briefly)

Interior - repainted February 1981

Metal siding placed over (8" x 3/4" wood) - fall 1980

Changed to combination storm windows - summer 1976

Changed to combination storm doors - summer 1973

Added 4' plywood lower outside wall of porch and rescreened upper - summer 1981

FORM COMPLETED BY: Norris A. Forum

DATE: 18 Jan 82



SURVEY FORM FOR 1930'S RESIDENCES (12)

ADDRESS: 1108 - East Kansas

13/392095/5318555

DESCRIPTION: Type P-3

SIDING: Wood _____ Asbestos _____ Metal X Green
White stucco entrance and red fireplace
Brick _____ Stone _____

DATE SIDING ADDED (if known): fall, 1980.

DATE GARAGE BUILT (if known): summer, 1934 (original)

STORM WINDOWS: Wood Frame _____ Aluminum Frame X.

STORM DOORS: Wood Frame _____ Aluminum Frame X.

CHANGE IN DOOR LOCATION: Yes _____ No X

CHANGE IN WINDOW LOCATION: Yes _____ No X

ORIGINAL PAINT SCHEME: Yes _____ No X

CHANGE IN PORCH STRUCTURE: Yes X No _____

AGE OF HOUSE (in years): 51 years

INTERIOR AND STRUCTURAL CHANGES (Fill in as necessary for each house): (briefly)

Added 1/2 bathroom and one bedroom in basement (date unknown)

Interior - repainted Sep 76

Metal siding placed over (8" x 3/4" wood) - fall 1980 -

Changed to combination storm windows - summer 1976

Changed to combination storm doors - summer 1973

Added 4' plywood lower outside wall of porch and rescreened upper - summer 1981

FORM COMPLETED BY: Norris A. Forum

DATE: 18 Jan 82



SURVEY FORM FOR 1930'S RESIDENCES (12)

ADDRESS: 1109 - East Kansas

13/392090/5318590

DESCRIPTION: Type P-4

Rust color
Log _____
SIDING: Wood X Asbestos _____ Metal _____

Brick _____ (Stone fireplace - native)

DATE SIDING ADDED (if known): summer , 19 34 (original)

DATE GARAGE BUILT (if known): Summer , 19 34 (original)

STORM WINDOWS: Wood Frame _____ Aluminum Frame X .

STORM DOORS: Wood Frame _____ Aluminum Frame X .

CHANGE IN DOOR LOCATION: Yes _____ No X

CHANGE IN WINDOW LOCATION: Yes _____ No X

ORIGINAL PAINT SCHEME: Yes X No _____

CHANGE IN PORCH STRUCTURE: Yes X No _____

AGE OF HOUSE (in years): 51 years

INTERIOR AND STRUCTURAL CHANGES (Fill in as necessary for each house): (briefly)

One bedroom in basement (date unknown)

Interior - repainted September 1976

Changed to combination storm windows - summer 1976

Changed to combination storm doors - summer 1973

Added 4' plywood lower outside wall of porch and rescreened upper - summer 1981

FORM COMPLETED BY: Norris A. Forum

DATE: 18 Jan 82



SURVEY FORM FOR 1930'S RESIDENCES (12)

ADDRESS: 1110 - East Kansas

13/39270/53186105

DESCRIPTION: Type P-2

SIDING: Wood _____ Asbestos _____ Metal X Blue
Brick _____ White stucco - entrance _____ Red brick fireplace
Stone _____

DATE SIDING ADDED (if known): fall, 1980.

DATE GARAGE BUILT (if known): summer, 1934 (original)

STORM WINDOWS: Wood Frame _____ Aluminum Frame X.

STORM DOORS: Wood Frame _____ Aluminum Frame X.

CHANGE IN DOOR LOCATION: Yes _____ No X

CHANGE IN WINDOW LOCATION: Yes _____ No X

ORIGINAL PAINT SCHEME: Yes _____ No X

CHANGE IN PORCH STRUCTURE: Yes X No _____

AGE OF HOUSE (in years): 51 years

INTERIOR AND STRUCTURAL CHANGES (Fill in as necessary for each house): (briefly)

Interior - repainted February 1980

Metal siding placed over (8" x 3/4" wood) - fall 1980

Changed to combination storm windows - summer 1976

Change to combination storm doors - summer 1973

Added 4' plywood lower outside wall of porch and rescreened upper - summer 1981

FORM COMPLETED BY: Norris A. Forum

DATE: 18 Jan 82



SURVEY FORM FOR 1930'S RESIDENCES (12)

ADDRESS: 1111 - East Kansas

13/392040/5318630

DESCRIPTION: Type P-3

SIDING: Wood _____ Asbestos _____ Metal X yellow
Brick _____ Stone _____ Red brick fireplace

DATE SIDING ADDED (if known): fall , 19 81 .

DATE GARAGE BUILT (if known): summer , 19 34 (original)

STORM WINDOWS: Wood Frame _____ Aluminum Frame X .

STORM DOORS: Wood Frame _____ Aluminum Frame X .

CHANGE IN DOOR LOCATION: Yes _____ No X

CHANGE IN WINDOW LOCATION: Yes _____ No X

ORIGINAL PAINT SCHEME: Yes _____ No X

CHANGE IN PORCH STRUCTURE: Yes _____ No X

AGE OF HOUSE (in years): 51 years

INTERIOR AND STRUCTURAL CHANGES (Fill in as necessary for each house): (briefly)

Interior - repainted February 1977
Metal siding placed over (8" x 3/4" wood) - fall 1980
Changed to combination storm windows - summer 1976
Changed to combination storm doors - summer 1973

FORM COMPLETED BY: Norris A. Forum

DATE: 18 Jan 82



SURVEY FORM FOR 1930'S RESIDENCES (12)

ADDRESS: 1112 - East Kansas

13/392010/5318645

DESCRIPTION: Type P-3

SIDING: Wood _____ Asbestos _____ Metal X Blue
Brick _____ Red brick entrance and fireplace
Stone _____

DATE SIDING ADDED (if known): fall , 1980 .

DATE GARAGE BUILT (if known): summer , 1934 (original)

STORM WINDOWS: Wood Frame _____ Aluminum Frame X .

STORM DOORS: Wood Frame _____ Aluminum Frame X .

CHANGE IN DOOR LOCATION: Yes _____ No X

CHANGE IN WINDOW LOCATION: Yes _____ No X

ORIGINAL PAINT SCHEME: Yes _____ No X

CHANGE IN PORCH STRUCTURE: Yes X No _____

AGE OF HOUSE (in years): 51 years

INTERIOR AND STRUCTURAL CHANGES (Fill in as necessary for each house): (briefly)

Interior - repainted June 1973

Metal siding placed over (8" x 3/4" wood) - fall 1980

Changed to combination storm windows - summer 1976

Changed to combination storm doors - summer 1973

Added 4" plywood lower outside wall of porch and rescreened upper - summer 1981

FORM COMPLETED BY: Norris A. Forum

DATE: 18 Jan 82



SURVEY FORM FOR 1930'S RESIDENCES (12)

ADDRESS: 1101 - Est Kansas Ave.

13/392120/5318335

DESCRIPTION: Type P-1

Outside - Dove Gray
Shakes
SIDING: Wood Asbestos _____ Metal _____
Entrance - Native Stone - Red Brick Fireplace
Brick _____ Stone

DATE SIDING ADDED (if known): Summer, 1934 (Original)

DATE GARAGE BUILT (if known): Summer, 1934 (Original)

STORM WINDOWS: Wood Frame _____ Aluminum Frame

STORM DOORS: Wood Frame _____ Aluminum Frame

CHANGE IN DOOR LOCATION: Yes _____ No

CHANGE IN WINDOW LOCATION: Yes _____ No

Outside - Dove Gray
ORIGINAL PAINT SCHEME: Yes No _____

CHANGE IN PORCH STRUCTURE: Yes No _____

AGE OF HOUSE (in years): 51 years

INTERIOR AND STRUCTURAL CHANGES (Fill in as necessary for each house): (briefly)

Added bathroom in basement (date unknown)

Interior repainted - February 1981

Removed partition to pantry, make kitchen larger - summer 1955

Changed to combination storm windows - summer 1976

Changed to combination storm doors - summer 1973

Added 4' plywood lower outside wall of porch and rescreened upper - summer 1981

FORM COMPLETED BY: Norris A. Forum

DATE: 18 Jan 82





1. Original Residences Historic District,
Ft. Peck Multiple Resource District
2. Ft. Peck, MT
3. Mark Calamar
4. 22 February 1985
5. Omaha District photo library
6. Looking south
7. Photograph No. 17



1. 1112 East Kansas Ave., Original Residences
Historic District, Ft. Peck Multiple
2. Ft. Peck, MT Resource District
3. Mark Calamar
4. 22 February 1985
5. Omaha District photo library
6. Looking southeast
7. Photograph No. 18



1. 1112 East Kansas Ave., Original Residences
Historic District, Ft. Peck Multiple
2. Ft. Peck, MT Resource District
3. Mark Calamar
4. 22 February 1985
5. Omaha District photo library
6. Looking west
7. Photograph No. 19



1. 1111 East Kansas Ave., Original Residences
Historic District, Ft. Peck Multiple
2. Ft. Peck, MT Resource District
3. Mark Calamar
4. 22 February 1985
5. Omaha District photo library
6. Looking west
7. Photograph No. 20



1. 1110 East Kansas Ave., Original Residences
Historic District, Ft. Peck Multiple
2. Ft. Peck, MT Resource District
3. Mark Calamar
4. 22 February 1985
5. Omaha District photo library
6. Looking west
7. Photograph No. 21



1. 1109 East Kansas Ave., Original Residences
Historic District, Ft. Peck Multiple
2. Ft. Peck, MT Resource District
3. Mark Calamar
4. 22 February 1985
5. Omaha District photo library
6. Looking west southwest
7. Photograph No. 21



1. 1108 East Kansas Ave., Original Residences
Historic District, Ft. Peck Multiple
2. Ft. Peck, MT Resource District
3. Mark Calamar
4. 22 February 1985
5. Omaha District photo library
6. Looking west
7. Photograph No. 22



1. 1107 East Kansas Ave., Original Residences
Historic District, Ft. Peck Multiple
2. Ft. Peck, MT Resource District
3. Mark Calamar
4. 22 February 1985
5. Omaha District photo library
6. Looking west
7. Photograph No. 23



1. 1106 East Kansas Ave., Original Residences
Historic District, Ft. Peck Multiple
2. Ft. Peck, MT Resource District
3. Mark Calamar
4. 22 February 1985
5. Omaha District photo library
6. Looking northwest
7. Photograph No. 24



1. 1105 East Kansas Ave., Original Residences
Historic District, Ft. Peck Multiple
2. Ft. Peck, MT Resource District
3. Mark Calamar
4. 22 February 1985
5. Omaha District photo library
6. Looking southwest
7. Photograph No. 25



1. 1104 East Kansas Ave., Original Residences
Historic District, Ft. Peck Multiple
2. Ft. Peck, MT Resource District
3. Mark Calamar
4. 22 February 1985
5. Omaha District photo library
6. Looking southwest
7. Photograph No. 26



1. 1103 East Kansas Ave., Original Residences
Historic District, Ft. Peck Multiple
2. Ft. Peck, MT Resource District
3. Mark Calamar
4. 22 February 1985
5. Omaha District photo library
6. Looking west
7. Photograph No. 27



1. 1102 East Kansas Ave., Original Residences
Historic District, Ft. Peck Multiple
2. Ft. Peck, MT Resource District
3. Mark Calamar
4. 22 February 1985
5. Omaha District photo library
6. Looking west
7. Photograph No. 28



1. 1101 East Kansas Ave., Original Residences
Historic District, Ft. Peck Multiple
2. Ft. Peck, MT Resource District
3. Mark Calamar
4. 22 February 1985
5. Omaha District photo library
6. Looking west
7. Photograph No. 29



1. 1101 East Kansas Ave., Original Residences
Historic District, Ft. Peck Multiple
2. Ft. Peck, MT Resource District
3. Mark Calamar
4. 22 February 1985
5. Omaha District photo library
6. Looking north
7. Photograph No. 30