



Riley- Cutler House  
11510 Pedee Creek Road  
Monmouth, Polk County, Oregon

Rusty Gorman Photo, 1979  
330 SE Viewmont  
Corvallis, Oregon 97330

1 of 19  
View of site before relocation

**JAN 14 1980**



Riley- Cutler House  
11510 Pedee Creek Road  
Monmouth, Polk County, Oregon

Photographer unknown, c. 1941  
Negative at 330 SE Viewmont  
Corvallis, Oregon 97330

2 of 19  
North elevation, c. 1941

**JAN 14 1980**



Riley-Cutler House  
11510 Pedee Creek Road  
Monmouth, Polk County, Oregon

Rusty Gorman Photo, 1979  
330 SE Viewmont  
Corvallis, Oregon 97330

3 of 19  
North elevation

**JAN 14 1980**



Riley-Cutler House  
11510 Pedee Creek Road  
Monmouth, Polk County, Oregon

Rusty Gorman Photo, 1979  
330 SE Viewmont  
Corvallis, Oregon 97330

4 of 19  
Detail of porch

JAN 14 1980



Riley-Cutler House  
11510 Pedee Creek Road  
Monmouth, Polk County, Oregon

Rusty Gorman Photo, 1979  
330 SE Viewmont  
Corvallis, Oregon 97330

5 of 19  
Detail of North elevation

JAN 14 1980



Riley-Cutler House  
11510 Pedee Creek Road  
Monmouth, Polk County, Oregon

Rusty Gorman Photo  
330 SE Viewmont  
Corvallis, Oregon 97330

6 of 19  
West elevation

JAN 14 1980



Riley-Cutler House  
11510 Pedee Creek Road  
Monmouth, Polk County, Oregon

Rusty Gorman Photo, 1979  
330 SE Viewmont  
Corvallis, Oregon 97330

7 of 19  
Bracket detail

**JAN 14 1980**



Riley-Cutler House  
11510 Pedee Creek Road  
Monmouth, Polk County, Oregon

Rusty Gorman Photo, 1979  
330 SE Viewmont  
Corvallis, Oregon 97330

JAN 14 1980

8 of 19

Bargeboard detail, East elevation



Riley-Cutler House  
11510 Pedee Creek Road  
Monmouth, Polk County, Oregon

Rusty Gorman Photo, 1979  
330 SE Viewmont  
Corvallis, Oregon 97330

9 of 19  
Detail of newel post

**JAN 14 1980**



Riley-Cutler House  
11510 Pedee Creek Road  
Monmouth, Polk County, Oregon

Rusty Gorman Photo, 1979  
330 SE Viewmont  
Corvallis, Oregon 97330

10 of 19  
Interior detailing

**JAN 14 1980**



Riley-Cutler House  
11510 Pedee Creek Road  
Monmouth, Polk County, Oregon

Rusty Gorman Photo, 1979  
330 SE Viewmont  
Corvallis, Oregon 97330

11 of 19  
Interior view facing  
Northwest

JAN 14 1980



North elevation showing removal  
of front porch. Pieces left in  
contact where possible, chemically  
stipped, neutralized, primed &  
painted before reassembly.

Riley-Cutler House  
11510 Pedee Creek Road  
Monmouth, Polk County, Oregon

Rusty Gorman Photo, 1979  
330 SE Viewmont  
Corvallis, Oregon 97330

12 of 19  
Removal of front porch

**JAN 14 1980**



North elevation showing removal  
of "onion" turret with crane.  
Crane also facilitated the removal  
of North attic gable wall and  
the West dormer assembly.

Riley-Cutler House  
11510 Pedee Creek Road  
Monmouth, Polk County, Oregon

Rusty Gorman Photo, 1979  
330 SE Viewmont  
Corvallis, Oregon 97330

13 of 19  
Removal of turret

JAN 14 1980



West/South elevation following  
removal & cataloging of siding  
facia's with fake rafter tails  
bargeboards, all 2nd story  
windows & interior trim & roof.

Riley-Cutler House  
11510 Pedee Creek Road  
Monmouth, Polk County, Oregon

Rusty Gorman Photo, 1979  
330 SE Viewmont  
Corvallis, Oregon 97330

14 of 19  
Upper wall frames

**JAN 14 1980**



North elevation showing removal of  
2nd story wall. Pieces left intact  
to minimize damage to fragile de-  
tails, & maximize accuracy during  
reassembly.

Riley-Cutler House  
11510 Pedee Creek Road  
Monmouth, Polk County, Oregon

Rusty Gorman Photo, 1979  
330 SE Viewmont  
Corvallis, Oregon 97330

15 of 19  
Dismantling continues

**JAN 14 1980**



West elevation showing removal of second story. Balloon construction was cut off at floor and later reconstructed in the platform style with original 19th century building materials.

Riley-Cutler House  
11510 Pedee Creek Road  
Monmouth, Polk County, Oregon

Rusty Gorman Photo, 1979  
330 SE Viewmont  
Corvallis, Oregon 97330

JAN 14 1980

16 of 19  
Dismantling almost complete



North elevation, west section of  
main house showing the move on  
July 1st, 1979, along Pedee Cr.  
Road. The East section preceeded  
the West during the move.

Riley-Cutler House  
11510 Pedee/Creek Road  
Monmouth, Polk County, Oregon

Rusty Gorman Photo, 1979  
330 SE Viewmont  
Corvallis, Oregon 97330

JAN 14 1980

17 of 19  
Relocation of West half of  
lower storey



Riley-Cutler House  
11510 Pedee Creek Road  
Monmouth, Polk County, Oregon

Rusty Gorman Photo, 1979  
330 SE Viewmont  
Corvallis, Oregon 97330

JAN 14 1980

18 of 19  
Reconstruction on new site,  
North elevation



Riley-Cutler House  
11510 Pedee Creek Road  
Monmouth, Polk County, Oregon

JAN 14 1980

Rusty Gorman Photo, 1979  
330 SE Viewmont  
Corvallis, Oregon 97330

19 of 19

Reconstruction on new site,  
West elevation



Riley-Cutler House  
11510 Pedee Creek Rd.  
Monmouth vicinity, Polk Co, OR  
1 of 2nd set of 11 - North  
(front) elevation at original  
site in Dallas

Rusty Gorman photo, 1979  
330 SE Viewmont  
Corvallis, OR 97330

MAR 26 1980



Riley-Cutler House  
11510 Pedee Creek Rd.  
Monmouth vic., Polk Co, Oreg.

2 of 2nd set of 11 - North  
(front) elevation at present

site, showing accurate restoration in progress.

Steve Waller photo, 1980

11510 Pedee Creek Road

Monmouth, OR 97361

MAR 26 1980



MAR 26 1980

Riley-Cutler House  
11510 Pedee Creek Rd.  
Monmouth vic., Polk Co, Ore.  
3 of 2nd set of 11 - Detail  
of front porch in process of  
re-assembly at present site.

Steve Waller photo, 1980  
11510 Pedee Creek Rd.  
Monmouth, OR 97361



MAR 26 1980

Riley-Cutler House  
11510 Pedee Creek Rd.  
Monmouth vic, Polk Co, Oregon  
4 of 2nd set of 11 - Detail  
of restored turret. Historic  
view of 1941 shows that dome  
shingling had fancy butts,  
whereas roof did not.  
Steve Waller photo, 1980  
11510 Pedee Creek Rd.  
Monmouth, OR 97361



Riley-Cutler House  
11510 Pedee Creek Rd.  
Monmouth vic, Polk Co, Oregon

5 of 2nd set of 11 - Detail  
of jigsaw work of porch and  
balconies on north (front)  
elevation at original site.

Rusty Gorman photo, 1979  
330 SE Viewmont  
Corvallis, OR 97330

MAR 26 1980



MAR 26 1980

Riley-Cutler House  
11510 Pedee Creek Rd.  
Monmouth vic, Polk Co, Oregon

6 of 2nd set of 11 - Detail  
of balconies, north (front)

elevation, in process of re-  
assembly at present site.

Steve Waller photo, 1980  
11510 Pedee Creek Rd.  
Monmouth, OR 97361



Riley-Cutler House  
11510 Pedee Creek Rd.  
Monmouth vic, Polk Co, Oregon  
7 of 2nd set of 11 - West (side  
elevation at original site,  
showing treatment of ell

Rusty Gorman photo, 1979  
330 SE Viewmont  
Corvallis, OR 97330

MAR 26 1980



MAR 26 1980

Riley-Cutler House  
11510 Pedee Creek Rd.  
Monmouth vic, Polk Co, Oregon

8 of 2nd set of 11 - West  
(side) elevation at present

---

site, showing accurate restoration in progress.

Steve Waller photo, 1980  
11510 Pedee Creek Rd.  
Monmouth, OR 97361



MAR 26 1980

Riley-Cutler House  
11510 Pedee Creek Rd.  
Monmouth vic, Polk Co, Oregon  
9 of 2nd set of 11 - Detail of  
chimney stack as reassembled,  
west elevation, present site.  
Steve Waller photo, 1980  
11510 Pedee Creek Rd.  
Monmouth, OR 97361



MAR 26 1980

Riley-Cutler House  
11510 Pedee Creek Rd.  
Monmouth vic, Polk Co, Oregon  
10 of 2nd set of 11 - South  
(rear) elevation at present  
site. Rear porch and gazebo  
is sympathetic to house in  
style, but not original.  
Steve Waller photo, 1980  
11510 Pedee Creek Rd.  
Monmouth, OR 97361

This elevation is not  
visible from the public  
right-of-way nor, generally,  
from the private access road.



MAR 26 1980

Riley-Cutler House  
11510 Pedee Creek Rd.  
Monmouth vic, Polk Co, Oregon  
11 of 2nd set of 11 - East  
(side) elevation at present  
site, showing accurate restor-  
ation in progress.

Steve Waller photo, 1980  
11510 Pedee Creek Rd.  
Monmouth, OR 97361