



Byron House

Keystone, SD

Carolyn Torma 1981

Historical Preservation Center

interior, hinge detail

Photo 1



Byron House

Keystone, SD

Carolyn Torma 1981

Historical Preservation Center

garage

Photo 2



Byron House

Keystone, S D

Carolyn Torma 1981

Historical Preservation Center

north wall

Photo 3



Byron House
Keystone, SD
Carolyn Torma 1981
Historical Preservation Center
east wall
Photo 4



Byron House

Keystone, SD

Carolyn Torma · 1981

Historical Preservation::Center
south wall

Photo 5



Byron House

Keystone, SD

Carolyn Torma 1981

Historical Preservation Center

detail, exterior

Photo 6



Byron House

Keystone, SD

Carolyn Torma 1981

Historical Preservation Center

west wall

Photo 7