

Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: November, 1981 Description (1 of 8): Front; photographer facing northeast.



Photographer: James R. Lockhart Negative Filed: Georgia Department J. Natural Resources Date: November, 1981 Description (2 of 8): Detail of front storefront; photographer facing southeast.



Columbus, Muscogee County, Georgia

Photographer: James R. Lockhart
Negative Filed: Georgia Department of

Natural Resources
Date: November, 1981
Description (3 of 8): Second floor south half front; photographer facing west.



Photographer: James R. Lockhart Negative Filed: Georgia Department of Natural Resources Date: November, 1981 Description (4 of 8): Second floor north half front; photographer facing west.



Photographer: James R. Lockhart
Negative Filed: Georgia Department of
Natural Resources
Date: November, 1981
Description (5 of 8): Second Floor central

wall; photographer facing southeast.



Photographer: James R. Lockhart

Megative Filed: Georgia Department of
Natural Resources

Date: November, 1981

Description (6 of 8): Second floor
south side rear; photographer facing

east.



Photographer: James R. Lockhart
Negative Filed: Georgia Department of
Natural Resources
Date: November, 1981
Description (7 of 8): First floor
south; photographer facing east.



Photographer: James R. Lockhart

photographer 'facing west.

Negative Filed: Georgia Department of Natural Resources Date: November, 1981 Description (8 of 8): Mechanical area immediately above first floor south side