



Murtha Site

Elk Point, Union County

South Dakota

John Burrows

1980

House

facing northwest

FEB 1 1982

JAN 1 2 1982



Murtha Site  
Elk Point, Union County

Photo 2  
SEP 23 1980

South Dakota

John Burrows

1980

FEB 1 1982

House

facing southeast



Photo 3

SEP 23 1980

Murtha Site  
Elk Point, Union County  
South Dakota  
John Burrows  
1980  
Barn  
facing northeast

FEB 1 1982



Murtha Site  
Elk Point, Union County  
South Dakota  
John Burrows  
1980  
Root Cellar  
facing west

SEP 23 1980

FEB 1 1982





Photo.

SEP 23 1980

Murtha Site  
Elk Point, Union County  
South Dakota  
John Burrows  
1980  
Brick Kiln  
facing north

FEB 1 1982



SEP 23 198

Murtha Site  
Elk Point, Union County  
South Dakota  
John Burrows  
1980  
Brick Kiln  
facing east

Photo (

FEB 1 1982



30 UN 8  
FEA 2  
4 00

Charles Murtha Brick Kiln and House

Elk Point, South Dakota

Steve Ruple

Historical Preservation Center

1980

FEB 1 1982

JAN 12 1982

Looking nw; detail of fuel port, surrounding  
ash glaze, remnant outline of sackwall

Photo 7



Charles Murtha Brick Kiln and House  
Elk Point, South Dakota

Steve Ruple

Historical Preservation Center  
1980

JAN 12 1982

Looking north showing ne quadrant, showing  
two fuel ports and partially cleaned exhaust

channel bricked in at the wall.

Photo 8

FEB 1 1982





Charles Murtha Brick Kiln and House

Elk Point, South Dakota

Steve Ruple

FEB 1 1982

Historical Preservation Center

1980

Looking east; showing a shallow feeder  
exhaust port

JAN 1 2 1982

Photo 9



TABLET  
TEXT  
L. 1  
L. 2

Small white object

Charles Murtha Brick Kiln and House

Elk Point, South Dakota

Steve Ruple

Historical Preservation Center  
1980

FEB 1 1982

JAN 1 2 1982

Looking north; detail of one of two exhaust  
channels. Port of chimney is bricked over.

Photo 10