



MORTON  
BUILDING

193

ONE  
WAY  
→

THE MORTON BUILDING (1) of 6  
Athens, Clarke County, Georgia

Photographer: James R. Lockhart

Date: December, 1978

Negatives filed Ga. Dept. of Natural Resources

Description: Front (West Washington Street)  
facade; photographer facing south-southeast.

*doc*  
OCT. 22 1979

11 SEP 1979

①

PHOTOGRAPH BY  
JAMES R. LOCKHART FOR  
DEPT. OF NATURAL RESOURCES  
HISTORIC PRESERVATION SECTION  
CREDIT MUST BE GIVEN

MORTON BUILDING 12/78  
ATHENS GA. CLARKE CO.  
FACING S.E.



THE MORTON BUILDING (2) 06 &  
Athens, Clarke County, Georgia

Photographer: James R. Lockhart

Date: December, 1978

Negatives filed Ga. Dept. of Natural Resources

Description: Front (West Washington Street)

doorway; photographer facing south-southeast.

OCT 22 1979 <sup>DOE</sup> 11 SEP 1979

(2)

PHOTOGRAPH BY  
JAMES R. LOCKHART  
DEPT. OF NATURAL RESOURCES  
HISTORIC PRESERVATION SECTION  
CREDIT MUST BE GIVEN

MORTON BUILDING 12/78  
CLARKE CO., ATHENS GA.  
FACING S.E.





THE MORTON BUILDING (3)  
Athens, Clarke County, Georgia

Photographer: James R. Lockhart

Date: December, 1978

Negatives filed Ga. Dept. of Natural Resources

Description: West (Hull Street) and rear elevations; and site of livery stable (right);  
photographer facing north. **11 SEP 1979**

*doe*  
OCT 22 1979

3

PHOTOGRAPH BY  
JAMES R. LOCKHART FOR  
DEPT. OF NATURAL RESOURCES  
HISTORIC PRESERVATION SECTION  
CREDIT MUST BE GIVEN

MORTON BUILDING 12/78  
CLARKE CO., ATHENS GA.  
FACING N.



THE MORTON BUILDING (4) 46  
Athens, Clarke County, Georgia

Photographer: James R. Lockhart

Date: December, 1978

Negatives filed Ga. Dept. of Natural Resources

Description: East elevation; photographer facing west-southwest.

OCT 22 1979 <sup>ROC</sup> 11 SEP 1979

4

PHOTOGRAPHER  
JAMES R. LOCKHART FOR  
DEPT. OF NATURAL RESOURCES  
HISTORIC PRESERVATION SECTION  
CREDIT MUST BE GIVEN

MORTON BUILDING 12/78  
CLARKE CO., ATHENS GA.  
FACING S.W.





THE MORTON BUILDING (5) of 6  
Athens, Clarke County, Georgia

Photographer: James R. Lockhart

Date: December, 1978

Negatives filed Ga. Dept. of Natural Resources


Description: View of the theater and stage from  
the balcony; photographer facing south-south-  
east.

OCT 22 1979 <sup>DOL</sup> 11 SEP 1979

5

PHOTOGRAPH BY  
JAMES R. LOCKHART FOR  
DEPT. OF NATURAL RESOURCES  
HISTORIC PRESERVATION SECTION  
CREDIT MUST BE GIVEN

MORTON BUILDING 12/78  
CLARKE Co. ATHENS GA.  
FACING S.



THE MORTON BUILDING (6) of 6  
Athens, Clarke County, Georgia

Photographer: James R. Lockhart

Date: December, 1978

Negatives filed Ga. Dept. of Natural Resources

Description: View of the theater and balcony  
from in front of the stage; photographer  
facing north-northwest.

OCT <sup>DOC</sup> 22 1979 11 SEP 1979

6

PHOTOGRAPH BY  
JAMES R. LOCKHART FOR  
DEPT. OF NATURAL RESOURCES  
HISTORIC PRESERVATION SECTION  
CREDIT MUST BE GIVEN

MORTON BUILDING 12/78  
CLARKE CO. ATHENS GA.  
FACING N.W.