

*McGraw-Hill*  
F.W. Winters House Rehabilitation  
*McGraw-Hill Book Company*

F.W. Winter's House

Bellevue, WA.

Katheryn H. Kraft

July 1991

Katheryn H. Kraft

West facade as viewed to the SE

108 12



F.W. Winters House

Bellevue, WA.

Katheryn H. Kratzt

July 1991

Katheryn H. Kratzt

West facade as viewed from the NW

2 at 12



F.W. Winters House  
Bellevue, WA.  
Katheryn H. Kraftt  
July 1991

Katheryn H. Kraftt  
South elevation as viewed to the north  
30512



F. W. Winters House

Bellvue, WA.

Kathergn H. Kraftt

July 1991

Kathergn H. Kraftt

East Elevation as viewed to the S.

4 of 12



F.W. Winters House

Bellevue, WA.

Katheryn H. Krafft

July 1991

Katheryn H. Krafft

North elevation and site as viewed  
to the SE

50512



F.W. Winters House

Bellevue, WA.

Katheryn H. Kraft

July 1991

Katheryn H. Kraft

Main stair at entry hall  
as viewed to the east

60512



A. W. Winters House  
Dellerue, WA.

Katherlyn H. Kraftst  
July 1991

Katherlyn H. Kraftst  
Living Room interior as  
viewed to the SE

705 12



F.W. Winters House

Bellvue, WA.

Katheryn H. Kraft

July 1991

Katheryn H. Kraft

Typical fireplace / tile overmantle

8 of 12



F.W. Winters House  
Bellevue, WA.

Katherlyn H. Kraftt  
July 1991

Katherlyn H. Kraftt  
View to the east of  
dining room/kitchen  
tile finishes

9 of 12



F.W. Winters House

Bellvue, WA.

Katheryn H. Krafft

July 1991

Katheryn H. Krafft

View to the SW of upper floor

bathroom / tile finishes (unrestored)

10 of 12



F. 22668

S. 17

1-6-39

(10)

5-24-5  
T.L. 84


"A"

F.W. Winters House  
Bellevue, WA,  
Unidentified

1-6-39 (1939)

Washington State Regional Archives, Seattle  
View to the SE of West Facade WA,

11 Oct 12



F. 22668

S. 17

1-6-39

(10)

5 - 24 - 5  
T. L. 84

"A" REAR

F.W. Winters House

Bellevue, WA.

Unidentified

1-6-39 (1939)

Washington State Regional Archives, Seattle

View to the NW of East Elevation

12 of 12