



Nobleville Milling Company Mill

Hamilton County, Indiana

Carol Ann Schweikert

June, 2001

Indiana Dept. of Historic Preservation and Archaeology

View looking Northeast

Photo # 1



Noblesville Milling Company Mill

Hamilton County, Indiana

Carol Ann Schweikert

June, 2001

Indiana Department of Historic Preservation and Archaeology

South facade looking South

Photo # 2



Noblesville Milling Company Mill

Hamilton County, Indiana

Carol Ann Schweikert

June, 2001

Indiana Department of Historic Preservation and Archaeology

East facade looking Northwest

Photo # 3



Noblesville Milling Company Mill

Hamilton County, Indiana

Carol Ann Schweikert

June, 2001

Indiana Department of Historic Preservation
and Archaeology

Northeast Corner looking Southwest

Photo # 11



Noblesville Milling Company Mill

Hamilton County, Indiana

Carol Ann Schweikert

June, 2001

Indiana Dept. of Historic Preservation and Archaeology

North and East facades looking Southwest

Photo # 5



Noblesville Milling Company Mill

Hamilton County, Indiana

Carol Ann Schweikert

June, 2001

Indiana Dept. of Historic Preservation and Archaeology

North facade looking Southeast

Photo # 6



Noblesville Milling Company Mill

Hamilton County, Indiana

Carol Ann Schweikert

June, 2001

Indiana Dept. of Historic Preservation and
Archaeology

West facade under awning looking Northeast

Photo # 7



Noblesville Milling Company Mill

Hamilton County, Indiana

Carol Ann Schweikert

June, 2001

Indiana Dept. of Historic Preservation and Archaeology

Roofline detail on South facade looking north

Photo #8

THE SPRINKLER HOIST
FOR THIS AREA IS
NO. 3
LOCATED IN
BOILER ROOM YARD



Noblesville Milling Company Mill

Hamilton County, Indiana

Carol Ann Schweikert

June, 2001

Indiana Dept. of Historic Preservation and Archaeology

Section E, first floor, looking east

Photo # 9

A black and white photograph of an industrial interior. The room features a high ceiling with exposed wooden joists and a network of pipes. Two prominent wooden columns support the structure. The walls are made of brick, with the lower portion showing signs of peeling paint or plaster. The floor is concrete with several large, dark, rectangular mats or patches. In the background, there are windows and a doorway. A sign is mounted on the wall in the distance.

BLDG. 4
5F.L.
LLOD
25-11

Noblesville Milling Company Mill

Hamilton County, Indiana

Carol Ann Schweikert

June, 2001

Indiana Dept. of Historic Preservation and Archaeology

Section A, Second floor, looking North

Photo # 10



11
8

Noblesville Milling Company Mill

Hamilton County, Indiana

Carol Ann Schweikert

June, 2001

Indiana Dept. of Historic Preservation and Archaeology

Section D, Second floor, looking Southeast

Photo # 11

BLDG. 7
SP 3.

BLDG.
7
SP. 3

INDIANA SEED

Noblesville Milling Company Mill

Hamilton County, Indiana

Carol Ann Schweikert

June, 2001

Indiana Dept. of Historic Preservation and Archaeology

Section E, Second floor, looking east

Photo # 12



Noblesville Milling Company Mill

Hamilton County, Indiana

Carol Ann Schweitzer

June, 2001

Indiana Dep. of Historic Preservation and Archaeology

Section F, second floor, looking South east

Photo # 13



Noblesville Milling Company Mill

Hamilton County, Indiana

Carol Ann Schweikert

June, 2001

Indiana Dept. of Historic Preservation and
Archaeology

Section A, third floor looking North

Photo # 14



Noblesville Milling Company Mill
Hamilton County, Indiana

Carol Ann Schweikert

June 2001

Indiana Dept. of Historic Preservation and Archaeology

Section B, third floor looking Northeast

Photo # 15



Noblesville Milling Company Mill

Hamilton County, Indiana

Carol Ann Schweikert

June, 2001

Indiana Department of Historic Preservation and
Archaeology

Joint between Sections A and B on the third floor
Looking East

Photo # 16



Noblesville Milling Company Mill

Hamilton County, Indiana

Carol Ann Schweikert

June, 2001

Indiana Dept. of Historic Preservation and Archaeology

Section C, third floor looking northeast

Photo # 17



Noblesville Milling Company Mill

Hamilton County, Indiana


Carol Ann Schweikert

June, 2001

Indiana Dept. of Historic Preservation Archaeology

Section A, fourth floor, looking North

Photo # 18



Noblesville Milling Company Mill

Hamilton County, Indiana

Carol Ann Schweikert

June, 2001

Indiana Dept. of Historic Preservation and
Archaeology

Section D, third floor, freight elevator, looking
North

Photo # 19