

Suisun Lodge #55. F & AM SEP 19 1978 Suisun City, California Photographer: Albert L. Hurtado March 17, 1978 Neagative at Office of Historic Preservation Sacramento

East elevation #1



Suisun Lodge #55, F & AM Suisun City, California Photographer: Albert L. Hurtado EP 15 1978 March 17, 1978

Negative at Office of Historic Preservation, S Sacramento East elevation, Suisun City streetscape #3



Suisun Lodge #55 F & AM Suisun City, California Photographer: Albert L. Hurtado March 17, 1978 Negative at Office of Historic Preservation, Sacramento East elevation DECIRIT #4



Suisun Lodge #55, F & AM Suisun City, California Photographer: Albert L. Hurtado March 17, 1978 Negative at Office of Historic Preservation, Sacramento East elevation, store front

#5



Suisun Lodge #55. F & AM Suisun City, California Photographer: Albert L. Hurtado March 17, 1978 Sacramento

Negativedat Office of Historic Preservation, East elevation, entryway

#6



Suisun Lodge #55, F & AM Suisun City, California SEL TO 1918 Photogrpher: Albert L. Hurtado March 17, 1978

Negative at Office of Historic Preservation,
Sacramento
East elevation, entryway, detail, iron column
#8




DEC 18 1978

Suisun Lodge #55. F & AM Suisun City, California Photographer: Albert L. Hurtado EP 19 1978 March 17, 1978 Negative at Office of Historic Preservation, Sacramento West elevation



Suisun Lodge #55, F & AM Suisun City, California Photographer: Albert L. Hurtado March 17, 1978 Negative at Office of Historic Preservation, Sacramento

Sacramento
West elevation, detail, metal sheathed fire
door over first story window



Suisun Lodge #55, F & AM Suisun City, California OLF LU WAS Photographer: Albert L. Hurtado March 17, 1978 Negative at Office of Historic Preservation, Sacramento West elevation, detail, hinge on firedoor

#11



Suisun Lodge #55, F & AM Suisun Oity, California Photographer: Ray Brown ca. 1976 Negative at P.O. Box 2269. Fairfield. CA Interior, main hall SEP 19 1978 #18