

Photo 1 Of/O View of main (southeast) facade.



Photo 2 0 10

View of Spring Hill from northeast showing one-room wing.



Photo 3 %/0 View of Spring Hill from south-

west showing gallery and ell.




Photo 4 00 10

Greek Revival portico & entrance on main (southeast) facade.

APR 2

y.) .



Photo 5  $\%/^{0}$  Greek mantle in east room.

APR 2 1980



Photo 6 of/O Interior view taken in east room. Note panelled treatment of door jamb. 2 JAN 22 1980



Photo 70810 Six-panel door leading to rear porch from east room.

APR 2 1980



Photo 8 % 10 Federal mantle in west room.

APR 2 1990 JAN 22 1990




Photo 9 04/0 Window treatment in west room.

APR 2 gar



APR 2 1900

Photo 10 %/0
Brick smokehouse in yard northwest of main house. Photo taken from west.

JAN 22 1980