



Sanderling Beach Club

Sarasota County, FLORIDA

①



Sanderling Beach Club

Sarasota County, FLORIDA

2



3

SANDERLING BEACH CLUB HISTORIC DISTRICT
SIEGA KEY, SARASOTA COUNTY, FL 5/16



Sanderling Beach Club

Sarasota County, FLORIDA

(7)



Sanderling Beach Club

Sarasota County, FLORIDA

5




Sanderling Beach Club

Sarasota County, FLORIDA

9





Sanderling Beach Club

Sarasota County, FLORIDA



Sanderling Beach Club

Sarasota County, FLORIDA

(8)



Sanderling Beach Club

Sarasota County, FLORIDA

9



Sanderling Beach Club

Sarasota County, FLORIDA

Q1



Sanderling Beach Club

Sarasota County, FLORIDA





Sanderling Beach Club

Sarasota County, FLORIDA

12



Sanderling Beach Club

Sarasota County, FLORIDA



14

Sandestling Beach Club

Sarasota Co. FL.

VOID →







NW CORNER



SUBSIDENCE OF
SLAB





TEMPORARY
SHORING

SIV CORNER



SMART PILING CAP →





A photograph showing a vertical crack in a concrete surface. The crack runs from the top to the bottom of the frame. To the left of the crack is a dark, textured material, possibly a tarp or insulation. To the right is a light-colored concrete surface. A white metal structure is visible at the top right. Handwritten black text and arrows point to specific features in the crack. The word "VOID" is written at the top, with an arrow pointing to a gap in the concrete. Below it, the text "REMAINING PORTION OF CEMENTIOUS MASS" is written, with two arrows pointing to the jagged, broken edges of the concrete within the crack.

VOID

REMAINING
PORTION OF
CEMENTIOUS
MASS