



Ehrhardt House  
Sacramento Co., CA  
Photographer: Hal Paris  
4/03

Negative location: Elk Grove Community  
Services Dist.

House in setting

#179



Ehrhardt House

Sacramento Co. CA

Photographer: Hal Paris

4/03

Negative location: Elk Grove Community  
Services Dist

Main elevation

#2 of 9



Ehrhardt House  
Sacramento Co. CA

Photographer: Hal Paris  
4/03

Negative location: Elk Grove Community Services  
District

N. Side of house

# 3 of 9





Ehrhardt House  
Sacramento Co., CA

Photographer: Hal Paris  
4/03

Negative location: Elk Grove Community  
Services District

S. Side of house showing window replacement

#4 of 9





Ehrhardt House

Sacramento Co, CA

Photographer: Hal Paris

4/03

Negative location: Elk Grove Community  
Services District

Rear of house

#5 of 9



EHRHARDT, WILLIAM HOUSE

SACRAMENTO COUNTY, CALIFORNIA


PHOTOGRAPHER: HAL PARIS

9/18/02

NEG. LOCATION: ELK GROVE COMMUNITY SERVICES DISTRICT

BEDROOM UPSTAIRS. DOOR TRIM IS PLAIN WOOD WITH  
NO EMBELLISHMENTS.

#6 of 9



EHRHARDT, WILLIAM HOUSE

SACRAMENTO COUNTY, CALIFORNIA

PHOTOGRAPHER: HAL PARIS

9/18/02

NEG. LOCATION: ELK GROVE COMMUNITY SERVICES DISTRICT

PANELING 3/4 UP THE DINING ROOM WALL WITH PLATE SHELF AT TOP.

#7 of 9





EHRHARDT, WILLIAM HOUSE

SACRAMENTO COUNTY, CALIFORNIA

PHOTOGRAPHER: HAL PARIS

9/18/02

NEG. LOCATION: ELK GROVE COMMUNITY SERVICES DISTRICT

THE STAIRCASE RAILING, BASES AND CAPITALS ARE  
STRAIGHT LINES WITH NO ORNATE CARVINGS,

#8 of 9



EHRHARDT, WILLIAM HOUSE

SACRAMENTO COUNTY, CALIFORNIA

PHOTOGRAPHER: HAL PARIS

9/18/02

NEG. LOCATION: ELK GROVE COMMUNITY SERVICES DISTRICT

TWO OUTBUILDINGS ON THE SOUTH SIDE OF THE HOUSE.  
CAMERA FACING EAST. OUTBUILDINGS ARE NON-CONTRIBUTING  
RESOURCES.

# 9 of 9