

YUNG SEE SAN FONG
16660 Cypress Way, Los Gatos,
Santa Clara County, California
Jane Lidz, HABS photo, July/August 1980

Negatives filed: Santa Clara County Historical
Heritage Commission - 70 West Hedding Street San Jose, California 95110

## #CA-2070-1 Exterior

Looking Northeast: south elevation, utility room addition in foreground; askew bedroom wing addition at far right.

PHOTO #1 of 6



YUNG SEE SAN FONG 16660 Cypress Way, Los Gatos Santa Clara County, California Jane Lidz, HABS photo, July/August 1980 Negatives filed: Santa Clara County Historical Heritage Commission - 70 West Hedding Street San Jose, California 95110 #CA-2070-3 Exterior Looking Northwest: south elevation, compatible third floor studio bedroom addition; narrow hillside driveway in foreground. PHOTO #2 of 6



YIING SEE SAN FONG 16660 Cypress Way, Los Gatos Santa Clara County, California Jane Lidz, HABS photo, July/August 1980

Heritage Commission - 70 West Hedding Street San Jose, California 95110 CA#2070-4 Exterior

Negatives filed: Santa Clara County Historical

Looking Northeast: south elevation, closeup of entry door at far left; top of driveway retaining wall; window treatment and sitting Buddha.

PHOTO #3 of 6



YUNG SEE SAN FONG
16660 Cypress Way, Los Gatos
Santa Clara County, California
Jane Lidz, HABS photo, July/August 1980

Negatives filed: Santa Clara County Historical Heritage Commission - 70 West Hedding Street San Jose, California 95110

## CA#2070-8 Interior

Looking Southwest: living room with fireplace cabinet, window treatment, termite-track pillars with decorative arch leading to kitchen and dining room.

PHOTO #4 of 6



16660 Cypress Way, Los Gatos Santa Clara County, California Jane Lidz, HABS photo, July/August 1980 Negatives filed: Santa Clara County Historical Heritage Commission - 70 West Hedding Street San Jose, California 95110 CA#2070 - Interior Looking South: living room fireplace with

carved panels. PHOTO #5 of 6

YUNG SEE SAN FONG



YUNG SEE SAN FONG
16660 Cypress Way, Los Gatos
Santa Clara County, California
Jane Lidz, HABS photo, July/August 1980

Negatives filed: Santa Clara County Historical Heritage Commission - 70 West Hedding Street San Jose, California 95110

## CA#2070-12 Interior

Looking Northwest: dining room with fixed window additions and typical view of wooded hillside environs; above windows, original wallpaper. PHOTO #6 of 6