YUNG SEE SAN FONG
16660 Cypress Way, Los Gatos,
Santa Clara County, California
Jane Lidz, HABS photo, July/August 1980

Negatives filed: Santa Clara County Historical Heritage Commission - 70 West Hedding Street - San Jose, California 95110

#CA-2070-1 Exterior

Looking Northeast: south elevation, utility room addition in foreground; askew bedroom wing addition at far right.

PHOTO #1 of 6

YUNG SEE SAN FONG
16660 Cypress Way, Los Gatos
Santa Clara County, California

Jane Lidz, HABS photo, July/August 1980

Negatives filed: Santa Clara County Historical Heritage Commission - 70 West Hedding Street San Jose, California 95110

#CA-2070-3 Exterior

Looking Northwest: south elevation, compatible third floor studio bedroom addition; narrow hillside driveway in foreground.

PHOTO #2 of 6

YUNG SEE SAN FONG
16660 Cypress Way, Los Gatos
Santa Clara County, California

Jane Lidz, HABS photo, July/August 1980

Negatives filed: Santa Clara County Historical Heritage Commission - 70 West Hedding Street San Jose, California 95110

CA#2070-4 Exterior

Looking Northeast: south elevation, closeup of entry door at far left; top of driveway retaining wall; window treatment and sitting Buddha.

PHOTO #3 of 6

YUNG SEE SAN FONG
16660 Cypress Way, Los Gatos
Santa Clara County, California

Jane Lidz, HABS photo, July/August 1980

Negatives filed: Santa Clara County Historical Heritage Commission - 70 West Hedding Street
San Jose, California 95110

CA#2070-8 Interior

Looking Southwest: living room with fireplace cabinet, window treatment, termite-track pillars with decorative arch leading to kitchen and dining room.

PHOTO #4 of 6

YUNG SEE SAN FONG
16660 Cypress Way, Los Gatos
Santa Clara County, California

Jane Lidz, HABS photo, July/August 1980

Negatives filed: Santa Clara County Historical Heritage Commission - 70 West Hedding Street San Jose, California 95110

CA#2070-?--Interior

Looking South: living room fireplace with carved panels.

PHOTO #5 of 6

YUNG SEE SAN FONG
16660 Cypress Way, Los Gatos
Santa Clara County, California

Jane Lidz, HABS photo, July/August 1980

Negatives filed: Santa Clara County Historical Heritage Commission - 70 West Hedding Street
San Jose, California 95110

CA#2070-12 Interior

Looking Northwest: dining room with fixed window additions and typical view of wooded hillside environs; above windows, original wallpaper.

PHOTO #6 of 6