



Photo 1

Photographer: William Henry Jackson Negative No. F-2147, F-19, 911 Colorado Historical Society, Denver, CO Date: October 28, 1870

Page 1 VA. DALE Stage CD.



From painting by William Henry Jackson Date: unknown Negative No. F-4789, Colorado Historical Society, Denver, CO





- Photo 3
- Gloria Mills
- May 1985
- Negative: Colorado Historical Society, Denver, CO
- View: looking northeast



Photo 4

Gloria Mills

May 1985

Negative: Colorado Historical

Society, Denver, CO

View: looking northwest



- Virginia Dale Stage Station Larimer County, CO
- Photo 5
- Gloria Mills
- May 1985
- Negative: Colorado Historical
- Society, Denver, CO
- View: detail of front (south) wall



- Virginia Dale Stage Station Larimer County, CO
- Photo 6
- Photographer: Gloria Mills May 1985
- Negative: Colorado Historical Society, Denver, CO
- View: detail of front (south) wall



- Virginia Dale Stage Station Larimer County, CO
- Photo 7
- Photographer: Gloria Mills May 1985
- Negative: Colorado Historical Society, Denver, CO
- View: looking southwest



- Virginia Dale Stage Station Larimer County, CO
- Photo 8
- Photographer: Gloria Mills May 1985
- Negative: Colorado Historical Society, Denver, CO
- View: detail of west wall



Photo 9

Photographer: Gloria Mills May 1985

Negative: Colorado Historical Society, Denver, CO

View: looking northeast



- Virginia Dale Stage Station Larimer County, CO
- Photo 10
- Photographer: Gloria Mills May 1985
- Negative: Colorado Historical Society, Denver, CO
- View: cellar entrance at front (south) of house