



O'Connor House  
St. Thomas, North Dakota

*Pembina Co.*

Photo credit: Unknown

Date of photo: 1910

Location of negative: State Historical Society of North Dakota  
Liberty Memorial Building  
Bismarck, North Dakota 58505

Historical photo of house from southwest

Photo 1 of 9

**MAY 28 1980**

JUL 3 1980





O'Connor House  
St. Thomas, North Dakota

*Pembina Co.*

Photo credit: Kurt Schweigert  
State Historical Society

Date of photo: October, 1979

Location of negative: State Historical Society of North Dakota  
Liberty Memorial Building  
Bismarck, North Dakota 58505

House from south

Photo 2 of 9

**MAY 28 1980**

**JUL 3 1980**



O'Connor House  
St. Thomas, North Dakota

*Pembina Co.*

Photo credit: Kurt Schweigert  
State Historical Society

Date of photo: October, 1979

Location of negative: State Historical Society of North Dakota  
Liberty Memorial Building  
Bismarck, North Dakota 58505

House from southeast

Photo 3 of 9

**MAY 28 1980**

JUL 3 1980





SEVENTH AV

O'Connor House  
St. Thomas, North Dakota

*Pembina Co.*

Photo credit: Kurt Schweigert  
State Historical Society

Date of photo: October, 1979

Location of negative: State Historical Society of North Dakota  
Liberty Memorial Building  
Bismarck, North Dakota 58505

House from northwest

Photo 4 of 9

**MAY 28 1980**

**JUL 3 1980**





O'Connor House  
St. Thomas, North Dakota

*Pembina Co.*

Photo credit: Kurt Schweigert  
State Historical Society

Date of photo: October, 1979

Location of negatives: State Historical Society of North Dakota  
Liberty Memorial Building  
Bismarck, North Dakota 58505

Feature, turret area of south side

Photo 5 of 9

**MAY 28 1980**

**JUL 3 1980**



O'Connor House  
St. Thomas, North Dakota

*Pembina Co.*

Photo credit: Kurt Schweigert  
State Historical Society

Date of photo: October, 1979

Location of negative: State Historical Society of North Dakota  
Liberty Memorial Building  
Bismarck, North Dakota 58505

Porch column capital

Photo 6 of 9

**MAY 28 1980**

**JUL 3 1980**





O'Connor House  
St. Thomas, North Dakota

*Pembina Co.*

Photo credit: Kurt Schweigert  
State Historical Society

Date of photo: October 1979


Location of negative: State Historical Society of North Dakota  
Liberty Memorial Building  
Bismarck, North Dakota 58505

Spindled stair balustrade at second floor landing.

Photo 7 of 9

**MAY 28 1980**

JUL 3 1980



O'Connor House  
St. Thomas, North Dakota

*Pembina Co.*

Photo credit: Kurt Schweigert  
State Historical Society

Date of photo: October, 1979

Location of negative: State Historical Society of North Dakota  
Liberty Memorial Building  
Bismarck, North Dakota 58505


Built-in china cabinet and door of stained Georgia pine,  
dining room.

Photo 8 of 9

**MAY 28 1980**

JUL 3 1980





O'Connor House  
Thomas, North Dakota

*Dembina Co.*

*top*

Photo credit: Kurt Schweigert

Date of photo: October, 1979

Location of negative: State Historical Society of North Dakota  
Liberty Memorial Building  
Bismarck, North Dakota 58505

Original acetylene gas lighting fixture in southeast  
bedroom on second floor.

Photo 9 of 9

**MAY 28 1980**

**JUL 3 1980**