

Ambassador Apartments		#1048		
Portland, Oregon	Multnomah County	V		
Taken By: Sheila Finch A I A	1978			

Negative: Office of Sheila Finch Portland, Oregon

Facing directly west. Shows eastern entrance recess.

JAN 29 1979

FEB 26 1979



Ambassador Apartments Portland, Oregon

Multnomah County


Taken By: Sheila Finch A I A

1978

JAN 2 9 1979

Negative: Office of Sheila Finch Portland, Oregon

Detail of east facade showing roof balustrade and top three floors on FEB 26 1979



#3078 FEB 26 1979 Ambassador Apartments Portland, Oregon Multnomah County

1978

Portland, Oregon

Taken By: Sheila Finch A I A

JAN 2 9 1979 Negative: Office of Sheila Finch

Detail of east facade showing third floor three-bay unit.



Portland,	Oregon		Multnomah County	FEB 2 6 1979
Taken By:	Sheila Finch A I A		1978	#4048
Negative:	Office of Sheila Fine Portland, Oregon	ch		


JAN 2 9 1979

Ambassador Apartments

Shows west side of building.



Portland, Oregon
Shows south side of building.



Taken By:	Sheila Finch A I A	1978	#648
Negative:	Office of Sheila Finch Portland, Oregon		JAN 2 9 1979

Taken at intersection of S W Sixth & Madison looking south west. Shows

Multnomah County

FEB 26 1979

Ambassador Apartments

north street facade.

Portland, Oregon



Taken By:	Sheila Finch A I A	1978			#70	78	
Negative:	Office of Sheila Finch Portland, Oregon			JA	W 291	1979	
Taken at i	ntersection of S W Sixth	& Madison	looking	south	west.	Shows	east

Multnomah County

FEB 26 1979

Ambassador Apartments

Portland, Oregon

street facade.



Taken by: The Oregon Journal

Negative: #46042 at the Oregon Historical Society

Portland, Oregon

#8078

JAN 2 9 1979

Taken at intersection of S W Sixth & Madison looking south west. Shows east and north street facades.

1932