


1. Jones, Theophilus, House
2. Wallingford, New Haven Co., CT
3. Karen Foster
4. August 1989
5. 40 Jones Road, Wallingford
6. West elevation
7. Photograph 1



1. Jones, Theophilus, House
2. Wallingford, New Haven Co., CT
3. Karen Foster
4. August 1989
5. 40 Jones Road, Wallingford
6. South elevation
7. Photograph 2





1. Jones, Theophilus, House
2. Wallingford, New Haven Co., CT
3. Karen Foster
4. August 1989
5. 40 Jones Road, Wallingford
6. Principal doorway
7. Photograph 3



1. Jones, Theophilus, House
2. Wallingford, New Haven Co., CT
3. Karen Foster
4. August 1989
5. 40 Jones Road
6. Southwest room, southeast corner
7. Photograph 4





1. Jones, Theophilus, House
2. Wallingford, New Haven Co., CT
3. Karen Foster
4. August 1989
5. 40 Jones Road, Wallingford
6. Southwest room, north wall
7. Photograph 5



1. Jones, Theophilus, House
2. Wallingford, New Haven Co., CT
3. Karen Foster
4. August 1959
5. 40 Jones Road, Wallingford
6. Northwest room, northwest corner
7. Photograph 6







1. Jones, Theophilus, House
2. Wallingford, New Haven Co., CT
3. Karen Foster
4. August 1989
5. 40 Jones Road, Wallingford
6. Northwest room, south wall
7. Photograph 7



1. Jones, Theophilus, House
2. Wallingford, New Haven Co., CT
3. Karen Foster
4. August 1989
5. 40, Jones Road, Wallingford
6. East center room, west wall
7. Photograph 8




1. Jones, Theophilus, House
2. Wallingford, New Haven Co., CT
3. Karen Foster
4. August 1989
5. 40 Jones Road, Wallingford
6. East center room, west wall
7. Photograph 9





1. Jones, Theophilus, House
2. Wallingford, New Haven Co., CT
3. Karen Foster
4. August 1989
5. 40 Jones Road, Wallingford
6. Lean-to attachment, washing terrace, well (looking northwest)
7. Photograph 10



1. Jones, Theophilus, House
2. Wallingford, New Haven Co., CT
3. Karen Foster
4. August 1989
5. 40 Jones Road, Wallingford
6. Batten door (behind storm door shown in Photograph 10)
7. Photograph 11.








1. Jones, Theophilus, House
2. Wallingford, New Haven Co., CT
3. Karen Foster
4. August 1989
5. 40 Jones Road
6. Main staircase
7. Photograph 12




1. Jones, Theophilus, House
2. Wallingford, New Haven Co., CT
3. Karen Foster
4. August 1989
5. 40 Jones Road, Wallingford
6. Cellar, chamfered beam
7. Photograph 13



1. Jones, Theophilus, House
2. Wallingford, New Haven Co., CT
3. Karen Foster
4. August 1989
5. 40 Jones Road, Wallingford
6. Barn workshop, carriage house (looking northwest)
7. Photograph 14





1. Jones, Theophilus, House
2. Wallingford, New Haven Co., CT
3. Karen Foster
4. August 1989
5. 40 Jones Road, Wallingford
6. Woodshed (looking northeast)
7. Photograph 15



1. Jones, Theophilus, House
2. Wallingford, New Haven Co., CT
3. Karen Foster
4. August 1989
5. 40' Jones Road
6. Icehouse (looking southeast)
7. Photograph 16





1. Jones, Theophilus, House
2. Wallingford, New Haven Co., CT
3. Karen Foster
4. August 1988
5. 40 Jones Road, Wallingford
6. Pigeon house (looking northeast)
7. Photograph 17