



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

SE Corner, 1 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

East facade, 2 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

Detail of East gable end

3 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

South facade, 4 of 33



John Churchman House
Near Calvert, Maryland
Geoffrey Henry 4/1986
Negatives at MHT
21 State Circle, Annapolis
Window on SE corner of S facade
5 of 33



John Churchman House
Near Calvert, Maryland
Geoffrey Henry 4/1986
Negatives at MHT
21 State Circle, Annapolis
Door on 2nd story of South
facade, 6 of 33



John Churchman House
Near Calvert, Maryland
Geoffrey Henry 4/1986
Negatives at MHT
21 State Circle, Annapolis
South facade of stone half
7 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

South facade, 8 of 33



John Churchman House
Near Calvert, Maryland
Geoffrey Henry 4/1986
Negatives at MHT
21 State Circle, Annapolis
South facade, 9 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

West facade, 10 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

Detail of West gable end

11 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

Cellar door, West facade

12 of 33



Something went wrong while we were encoding this page.
Please check the log file to find out the details.

John Churchman House
Near Calvert, Maryland
Geoffrey Henry 4/1986
Negatives at MHT
21 State Circle, Annapolis
Detail of stonework on SW
corner, 13 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

NW corner, 14 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

N facade of stone half

15 of 33



John Churchman House
Near Calvert, Maryland
Geoffrey Henry 4/1986
Negatives at MHT
21 State Circle, Annapolis
N facade, 16 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

NE corner of brick half

17 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

E facade, 18 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

Barn east of house looking NE

19 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

Detail of fireplace in NW room

2nd story, 20 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

Detail of panelled door on

1st floor, 21 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

Stairs leading to attic in

brick half, 22 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

Detail of original pent roof

support, 23 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

Detail of mantel in west room,

1st floor, 24 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

Stairs leading to 2nd floor in

brick half, 25 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

Detail of fireplace in SW room,
1st floor, stone half, 26 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

Detail of drawer and cupboard, SW
room, 1st floor, stone half, 27 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

Stairway, s tone half, 28 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

Fireplace, E room, brick half, 29 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

Corner cupboard, E room, 30 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

Panelled door, W room, brick half

31 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

Fireplace, W room, brick half

32 of 33



John Churchman House

Near Calvert, Maryland

Geoffrey Henry 4/1986

Negatives at MHT

21 State Circle, Annapolis

Detail of water table & cellar
window, South facade, **33** of 33