

Photo No. 1
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
Date: February, 1977

View: From west, showing west facade of Factory H.



Photo No. 2
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
Date: February, 1977

View: From southwest, showing west facade and south end of Factory H and south facade of Factory W.



Photo No. 3
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
Date: February, 1977

View: From south, showing John R. Street, east facade of Factory H, and west facades of Factories W, X, Y, Z, 3, 4, 5; Craneways WX, XY, YX; and Tracks 13, 14, and 16.



Photo No. 4

By: Ralph J. Christian, AASLH Negative at: Historic Sites Survey Date: February, 1977

View: Interior of Factory W showing hollow column air distribution system.



Photo No. 5
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
Date: February, 1977

View: Interior of Craneway WX.



Photo No. 6
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
Date: February, 1977

View: From west, showing west end of Building 076, north facades of Building 098 and K, and north end of Factory H.



By: Ralph J. Christian, AASLH

Photo No. 7

of Factory AA.

Negative at: Historic Sites Survey Date: February, 1977 View: From west, showing front (west) facade of the Sales and Service Building and portion of west facade



Photo No. 8
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
Date: February, 1977

View: From north, showing north ends of Sales and Service Building and Executive Garage and north end and portion of west facade of Factory AA.