


3/20 View east along 1500 block of Hollins


Street with Mencken House the fifth house from the left















13/20 Interior, first floor, view of southeast corner of kitchen, transomed door is original back entrance into garden




14/20 Interior, second floor, northwest corner of front room which Mencken used as a study



15/20 Interior, Third floor, view of northcorner of front room









4/20 View of 1500 block of Hollins Street from Union Square with Mencken House in center of photograph









9/20 Interior, first floor, view from back parlor into front parlor Ş Ì







12/20 Interior, first floor, view of north wall of dining room