

Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: June 1984 Description (1 of 13): Front facade of house; photographer facing northeast.



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: June 1984 Description (2 of 13): Front facade and northwest side; photographer facing northeast.

~



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: June 1984 Description (3 of 13): Southeast side of house: photographer facing west.



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: June 1984 Description (4 of 13): Rear and southeast side of house; photographer facing west.



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: June 1984 Description (5 of 13): Detail of front entrance; photographer facing northwest.



. *

JACKSON-JOHNS HOUSE Winder, Barrow County, Georgia

Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: June 1984 Description (6 of 13): First-floor stair hall; photographer facing east.



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: June 1984 Description (7 of 13): First-floor west front room; photographer facing north.



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: June 1984 Description (8 of 13): First-floor east front room; photographer facing east.



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: June 1984 Description (9 of 13): First-floor east central room; photographer facing north.



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: June 1984 Description (10 of 13): Second-floor central hall; photographer facing northeast.



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: June 1984 Description (11 of 13): Second-floor east front room; photographer facing southeast.



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: June 1984 Description (12 of 13): Second-floor west front room; photographer facing north.



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: June 1984 Description (13 of 13): Attic; photographer facing southwest.