



St. Patrick's Church
Cumming vic., Madison Co., Iowa
Credit: Windshield Survey

Date: 1976

DEC 12 1978

Neg. at: Div. Historic Preserva-
tion, Iowa City

View: from southeast

OCT 10 1978



St. Patrick's Church
Cumming vic., Madison Co., Iowa
Credit: Windshield Survey
Date: 1976
Neg. at: Div. Historic Preserva-
tion, Iowa City
View: front (north) elevation

DEC 12 1978

001 10 1978



St. Patrick's Church

Cumming vic., Madison Co., Iowa

Credit: M.H. Bowers

Date: 1978

DEC 12 1978

Neg. at: Div. Historic Preservation

Iowa City IA

View: looking SSE from north of
the church

OCT 10 1978



St. Patrick's Church

Cumming vic., Madison Co., Iowa

Credit: M.H. Bowers

Date: 1978

DEC 12 1978

Neg. at: Div. Historic Preserva-
tion, Iowa City

View: looking SE from NE corner
of church

OCT 10 1978