Form No. 10-300 REV. (9/77)

DATA SHEET UNITED STATES DEPARTMENT

NATIONAL PARK SERVICE

#### NATIONAL REGISTER OF HISTORIC PLACES **INVENTORY -- NOMINATION FORM**

	レ	h	O	6	8	3	L	1	2
Ĩ	OR			ONL					

RECEIVED AUG 2 9 1978

DATE ENTERED

1979 MAR 7

	SEE II	NSTRUCTIONS IN HOM	TO COMPLETE NAT	IONAL REGISTER FORMS	S
			- COMPLETE APPLIC		
1	NAME				
	HISTORIC				
	German	Evangelical Reform	ed Church ( <del>Zoar C</del>	ongregation)	
	AND/OR COMMON				
_	Zoar	Church			
	LOCATION	N of newsta			
	STREET & NUMBER	aka Township			
	CITY, TOWN			NOT FOR PUBLICATION CONGRESSIONAL DISTR	ICT
	Newton			Fourth	
	STATE I OWA		CODE	county Jasper	CODE A 9 9
	CLASSIFIC	ATION		·····	
	0.1750.0DV				
	CATEGORY	OWNERSHIP	STATUS		ENTUSE
		PUBLIC X_private			MUSEUM
				COMMERCIAL	PARK
			WORK IN PROGRESS		PRIVATE RESIDENCE
	SITE	PUBLIC ACQUISITIO		ENTERTAINMENT	X_RELIGIOUS
	OBJECT		XYES: RESTRICTED	GOVERNMENT	SCIENTIFIC
		BEING CONSIDERED	YES: UNRESTRICTED	INDUSTRIAL MILITARY	TRANSPORTATION
-					
	<b>OWNER OF</b>	PROPERTY			
	NAME				
	Zoar C	hurch Corporation	·		
	STREET & NUMBER				
	R.R.	]			
	CITY, TOWN			STATE	
	Newt			lowa 50208	······································
1	LOCATION	OF LEGAL DESC	CRIPTION		
•	COURTHOUSE,	·			
	REGISTRY OF DEEDS,E	TC. Jasper County	Courthouse		
	STREET & NUMBER	Jusper county			<b>_</b>
~	CITY, TOWN			STATE	<u></u>
		wton		lowa	
6		TATION IN EXIS	TING SURVEY		
	DATE		FEDERAL	LSTATECOUNTYLOCAL	
	DEPOSITORY FOR SURVEY RECORDS	······································			<u></u>
	CITY, TOWN			STATE	·····

# 7 **DESCRIPTION**

v	CONDITION	CHECK ONE	<b>CHECK ONE</b> $\underline{X}_{ORIGINAL SITE}$	
A EXCELLENT	DETERIORATED	UNALTERED		
GOOD	RUINS	ALTERED	MOVED DATE	
FAIR	UNEXPOSED			

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This church is situated on rising ground above a county road in the north central part of the county. The church, with cemetery to the rear, is surrounded by rolling cropland. The churchyard and cemetery are set off by a frame of deciduous and evergreen trees, which, besides acting as an effective windbreak, give the property an intimate feeling in the middle of very open country.

Built in 1892, the Zoar church is a gable-roofed building of frame construction on a rock-faced stone foundation. It measures  $36' \times 59'$ , with an  $8' \times 16'$  chancel at the south end. On the west side is a small vestibule, with board-and-batten exterior walls. This vestibule, added in 1961, is now the main entrance to the sanctuary.

At the northeast corner of the church is a bell tower, with high-pitched roof, the bracketted cornice of which is broken on each side by gablets faced with scalloped shingling. This shingling is also found on the front gable end. Narrow clapboarding covers the exterior walls, except in the area between the foundation and sill level, which is faced with narrow, vertical siding.

Sash windows in the sanctuary and chancel have pointed arches, and are set in simple surrounds. The two doorways on the east side have shallow triangular arches and are sheltered by small gable rooflets. The doorway located at the base of the belltower was originally the main entrance, and is served by a flight of wooden steps. The belltower has openings at three levels. On the bottom level, paired sash are topped with a flat pediment which repeats the shape of the roof over the tower entrance. Paired sash windows are also found on the second level, on east and north sides of the tower. Openings in the bellchamper were originally rectangular, with louvres. The louvres have been removed, and the bpenings now have triangular tops.

As is the case with many of lowa's rural churches, the exterior of the Zoar church has been quite well preserved. The original interior, however, has been "modernized". When first finished, the sanctuary featured wainscoting, and plastered walls with stencilling above the chair rail and below the cornice level. A tall panel, with pointed arch, was stencilled on the rear wall of the chancel, with John 14:6 written in German within the arch. In 1937, acoustic tile and "panelling" covered walls and ceiling (although the wainscoting was preserved) and the verse from John rewritten in English. Most of the present furnishings are of 20th century vintage.

#### PERIOD **AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW** ----PREHISTORIC \_\_\_ARCHEOLOGY-PREHISTORIC \_\_COMMUNITY PLANNING \_\_\_LANDSCAPE ARCHITECTURE \_\_\_\_RELIGION \_\_\_1400-1499 \_\_ARCHEOLOGY-HISTORIC \_\_CONSERVATION \_\_\_LAW \_\_SCIENCE \_\_AGRICULTURE \_\_LITERATURE \_\_ECONOMICS \_\_\_SCULPTURE X ARCHITECTURE \_\_\_1600-1699 \_\_EDUCATION \_\_\_MILITARY \_\_SOCIAL/HUMANITARIAN \_\_\_1700-1799 \_\_ART \_\_\_ENGINEERING \_\_\_MUSIC \_\_\_THEATER \_\_X1800-1899 \_\_\_COMMERCE \_\_PHILOSOPHY \_\_\_EXPLORATION/SETTLEMENT ....TRANSPORTATION \_\_\_1900-\_\_COMMUNICATIONS \_INDUSTRY \_\_\_POLITICS/GOVERNMENT \_\_OTHER (SPECIFY) \_\_INVENTION SPECIFIC DATES **BUILDER/ARCHITECT** 1892

**8 SIGNIFICANCE** 

STATEMENT OF SIGNIFICANCE(See continuation sheet for revision of Paragraph 1 of this section)

The principal significance of this church lies in its details and variety of surface textures, which add particular character to an otherwise potentially plain structure. When first erected, the church was painted in several colors, which brought out the various shapes and wall textures (pointed arches, window pediments, scalloped shingling, horizontal and vertical siding, and the "stickwork" on the tower and below the window sills). Painting the church a flat white has, unfortunately, somewhat obscured these features. Nonetheless, the attention given to detail on the church suggests quality craftsmanship and a certain creative imagination on the part of the immigrants who built it.

The Zoar Congregation of the German Evangelical Reformed Church was organized in 1876 by immigrants, many of whom lived in Freeport, Illinois, before coming to Jasper County in the late 1860's. One other church of this denomination, at Baxter (approximately 6 miles to the west), was founded in 1869. Unlike the Baxter church, the Zoar church served an exclusively rural constituency, since Malaka Township did not (and does not) have any villages or towns. The first Zoar church, erected shortly after the congregation was organized, was a small and simple frame building. The present church is located slightly south and west of the original building (long since dismantled) and was built, like the first, by members of the congregation.

The parsonage, located to the east of the church, was sold in 1957 and is now a private residence.

The cemetery, located directly behind the church, is included in this nomination as an integral part of the building's environment (see aerial photo). The first burials were in 1877.

### 9 MAJOR BIBLIOGRAPHICAL REFERENCES

Centennial Committee, Zoar Church. Zoar Reformed Church, Newton, Iowa. Privately printed, 1976. Zoar Reformed Church, Record Book 1876-1907. Property of Zoar Church


Weaver, James B. (ed.) Past and Present of Jasper County, Iowa. Indianapolis: B.F. Bowen and Co., 1912. Vol. 1, pp. 309, 185-186.

# **10 GEOGRAPHICAL DATA**

ACREAGE OF NOMINATED PROF		-		
QUADRANGLE NAME <u>Des</u> UTM REFERENCES	Moines, Iowa	QU	ADRANGLE SCALE 1:2	50,000
A[1,5] [4]9,8]4,0,	0 4,62,913,0,0	в Ц		
ZONE EASTING	NORTHING	ZONE EASTIN	NORTHING	
ELII		FL_i LI		
GLILLI		н Ц		
VERBAL BOUNDARY DESC		· · · · · · · · · · · · · · · · · · ·		n e la companya da companya
Part of the North	half of the Northeas	t quarter of Sect	ion 23, Township	81 Range
19 commencing at t	he northeast corner of	of said section r	unning thence wes	st <b>3</b> 5
rods, thence south	16 rods, thence eas	t 35 rods, thence	<u>north 16 rods to</u>	
LIST ALL STATES AN	D COUNTIES FOR PROPERTIN	ES OVERLAPPING STAT	E OR COUNTY BOUNDA	or begin
STATE	CODE	COUNTY		ning. CODE
		*	<i>•</i>	
STATE	CODE	COUNTY		CODE
Marian Bowi ORGANIZATION Zoar Church	e Historical Committe	ee	DATE	
STREET & NUMBER			TELEPHONE	
290 NE 80	th St, Route #2		and the second	
CITY OR TOWN	5	lo	state owa 50237	
12 STATE HISTORIC THE EVA	C PRESERVATION		THE STATE IS:	:
NATIONAL	STATE		LOCAL X	
As the designated State Historic hereby nominate this property f criteria and procedures set forth STATE HISTORIC PRESERVATION	or inclusion in the National Re by the National Park Service			
TITLE Director, Div	ision of Historic Pre	eservation	DATE 8/24/7	18
FOR NPS USE ONLY I HEREBY CERTIFY THAT TH	IS PROPERTY IS INCLUDED I	N THE NATIONAL REGIS	STER DATE 3.7	2.9
KEEPER OF THE NATION		Z>>	^	
ATTEST: William H	. Branhan		DATE 3. 2 · 7	9
CHIEF OF RECISTRATION				9 <b>4</b> •

#### UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

#### NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM



German Evangelical Reformed Church, Newton vic., Jasper Co., Iowa

CONTINUATION SHEET ITEM NUMBER 8 PAGE

(revision of Paragraph 1, Statement of Significance)

This church is significant as an example of a type of frame church found frequently in rural areas of lowa (and certainly also elsewhere in the Midwest), either in the the country or in small towns. This type, attributed for the most part to the last two decades of the 19th century, and erected mostly by Protestant denominations, is in plan generally either rectangular, with a simple front gable, or cross-shaped, with an intersecting gable roof. An off-center, full-length tower, often tucked into the re-entrant angle of a cross-plan church, is a ubiquitous feature. Decorative articulation consists generally of elements borrowed from the Stick Style and the Queen Anne -- variations in surface materials and textures (shingles, usually in gable ends and at the tops of towers, clapboards and beaded tongue-in-groove siding), a network of "sticks" dividing the wall surface into discrete areas and engaging the frames of openings, and touches of decoration in the Eastlake style. Windows vary in shape, but generally the major windows have pointed heads, either flatsided or arched.

The Zoar church deserves recognition as a highly representative example of this type. It is, furthermore, extremely well-preserved, having lost on the exterior only its louvred shutters, the original stair railing, an early chimney on the east side of the building, and occasional pieces of decorative detail. An early shingle roof, it might be noted, is preserved on the tower. The articulation of the walls into different surface areas was originally emphasized by a multi-color paint scheme, but this building is now painted uniformly white.