



84-A-56

Windham Village Historic District

Windham, Vermont

Credit: Gina Campoli

Date: February, 1984

Negative Filed at Vermont Division for
Historic Preservation

Description: TH 1, #'s 5, 6, 7, 8, 10; View
looking North

Photograph 1



Windham Village Historic District

Windham, Vermont

Credit: Gina Campoli

Date: February, 1984

Negative Filed at Vermont Division for
Historic Preservation

Description: TH 1, #'s 5, 6, 7; View looking
Southwest

Photograph 2

84-A-56



Windham Village Historic District

Windham, Vermont

Credit: William Chapman

Date: August, 1982

Negative Filed at Vermont Division for
Historic Preservation

Description: Stone wall and view east from
Light House (#3); View looking east

Photograph 3



82-206-3

Windham Village Historic District

Windham, Vermont

Credit: William Chapman

Date: August, 1982

Negative Filed at Vermont Division for
Historic Preservation

Description: Old Mack Place-Reilly House (#1);
View looking Northwest

Photograph 4



82-207 #18

Windham Village Historic District
Windham, Vermont
Credit: William Chapman
Date: August, 1982
Negative Filed at Vermont Division for
Historic Preservation
Description: Adrian House (#2); View
looking Northwest
Photograph 5



Windham Village Historic District

Windham, Vermont

Credit: Gina Campoli

Date: February, 1984

Negative Filed at Vermont Division for
Historic Preservation

Description: Light House (#3); View looking
West

Photograph 6

84-A-56



Windham Village Historic District
Windham, Vermont

Credit: William Chapman

Date: August, 1982

Negative Filed at Vermont Division for
Historic Preservation

Description: Bennett House (#4); View look-
ing west

Photograph 7



82-207 #1

Windham Village Historic District

Windham, Vermont

Credit: William Chapman

Date: August, 1982

Negative Filed at Vermont Division for
Historic Preservation

Description: Bennett Barn (#4A); View
looking northwest

Photograph 8



84-A-56

Windham Village Historic District

Windham, Vermont

Credit: Gina Campoli

Date: February, 1984

Negative Filed at Vermont Division for

Historic Preservation

Description: Chapman House (#5); View

looking Southwest

Photograph 9



Windham Village Historic District

Windham, Vermont

Credit: Gina Campoli

Date: February, 1984

Negative Filed at Vermont Division for
Historic Preservation

Description: Harris-Moore House (#6); View
looking Southwest

Photograph 10

84-A-56



Windham Village Historic District
Windham, Vermont
Credit: William Chapman
Date: August, 1982
Negative Filed at Vermont Division for
Historic Preservation
Description: Smith-Hall House (#7); View
looking Northwest
Photograph 11



84-A-56

Windham Village Historic District

Windham, Vermont


Credit: Gina Campoli

Date: February, 1984

Negative Filed at Vermont Division for
Historic Preservation

Description: The Old Congregational Church
Parsonage-Orlando House(#9); View looking
Northwest

Photograph 12



82-206-17

Windham Village Historic District
Windham, Vermont

Credit: William Chapman

Date: August, 1982

Negative Filed at Vermont Division for
Historic Preservation

Description: Congregational Church (#10);

View looking north

Photograph 13



Windham Village Historic District
Windham, Vermont

Credit: Gina Campoli

Date: February, 1984

Negative Filed at Vermont Division for
Historic Preservation

Description: Historic Photograph of the
Harris Store once located at the site of #11;
no date for photo; View looking Northeast
Photograph 14

84-A-56



Windham Village Historic District

Windham, Vermont

Credit: Gina Campoli

Date: February, 1984

Negative Filed at Vermont Division for
Historic Preservation

Description: Historic photograph of the Harris
Store once located at the site of #11; no
date for photo; #'s 6 and 5 visible on left
and right; View looking East

Photograph 15



82-207#4

Windham Village Historic District
Windham, Vermont
Credit: William Chapman
Date: August, 1982
Negative Filed at Vermont Division for
Historic Preservation
Description: Hemion House (#12); View
looking southeast
Photograph 16



82-207 #15

Windham Village Historic District

Windham, Vermont

Credit: William Chapman

Date: August, 1982

Negative Filed at Vermont Division for
Historic Preservation

Description: Old Congregational Parsonage-
Dr. Mill's House (#13); View looking
west.

Photograph 17



Windham Village Historic District

Windham, Vermont

Credit: Gina Campoli

Date: February, 1984

Negative Filed at Vermont Division for
Historic Preservation

Description: The Old Congregational Parsonage-

Mills House (#13) and Mills Shed (#13A);

View looking Northeast

Photograph 18

84-A-56