

**HISTORIC RESOURCES INVENTORY**  
BUILDING AND STRUCTURES

STATE OF CONNECTICUT  
CONNECTICUT HISTORICAL COMMISSION  
59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106  
(203) 566-3005

Item #428  
1. BUILDING NAME (if known) \_\_\_\_\_

2. TOWN, CITY, VILLAGE, OR COUNTY  
Windsor  
Hartford

3. STREET AND NUMBER (incl. if in front)  
411-413 Windsor Avenue, map 69, block 8, lot 17; .56 acre

4. OWNER'S NAME  
Joseph F. and Lys Glonfriddo, 411 Windsor Ave., CT 06095

5. USE (if known) \_\_\_\_\_

6. DISTRICT  
Hartford North

7. DATE OF PHOTOGRAPH  
1/18/69, 4/5/30, 4/6/31, 6/5/0

8. SITE NO. \_\_\_\_\_

9. MAP REFERENCE  
Hartford North

10. PHOTOGRAPHED BY  
MNR  JR  Actual  Potential

11. IDENTIFICATION

12. TYPE OF BUILDING OR STRUCTURE  
Residential

13. DATE OF CONSTRUCTION  
c. 1825

14. INTERIOR ACCESSIBLE  
Yes  No  Same

15. EXTERIOR VISIBLE FROM PUBLIC ROAD  
Yes  No  Same

16. SIGNIFICANCE

17. HISTORICAL OR ARCHITECTURAL IMPORTANCE

18. DESCRIPTION

19. MATERIALS

20. CONDITION

21. SIGNIFICANCE

22. PHOTOGRAPHER'S NAME  
Michael K. O'Leary

23. DATE  
7/10/81

24. NEGATIVE ON FILE  
CHC, Sheet #22

25. PLACE  
East (front)

26. PHOTOGRAPH

27. COMMENTS

28. SOURCES

29. COMPILED BY

30. PHOTOGRAPHER'S NAME

31. DATE

32. NEGATIVE ON FILE

33. PLACE

34. PHOTOGRAPH

35. COMMENTS

36. SOURCES

37. COMPILED BY

38. PHOTOGRAPHER'S NAME

39. DATE

40. NEGATIVE ON FILE

41. PLACE

42. PHOTOGRAPH

43. COMMENTS

44. SOURCES

45. COMPILED BY

46. PHOTOGRAPHER'S NAME

47. DATE

48. NEGATIVE ON FILE

49. PLACE

50. PHOTOGRAPH

51. COMMENTS

52. SOURCES

53. COMPILED BY

54. PHOTOGRAPHER'S NAME

55. DATE

56. NEGATIVE ON FILE

57. PLACE

58. PHOTOGRAPH

59. COMMENTS

60. SOURCES

61. COMPILED BY

62. PHOTOGRAPHER'S NAME

63. DATE

64. NEGATIVE ON FILE

65. PLACE

66. PHOTOGRAPH

67. COMMENTS

68. SOURCES

69. COMPILED BY

70. PHOTOGRAPHER'S NAME

71. DATE

72. NEGATIVE ON FILE

73. PLACE

74. PHOTOGRAPH

75. COMMENTS

76. SOURCES

77. COMPILED BY

78. PHOTOGRAPHER'S NAME

79. DATE

80. NEGATIVE ON FILE

81. PLACE

82. PHOTOGRAPH

2 story masonry dwelling, "L" shaped in plan with pitched roof. House has a box cornice with complete return across the gable-end. Gable has an elliptical window opening (window has been removed). Penetration in the main block is symmetrical, 3 bays wide by 2 bays deep. Each bay has 6 x 6 sash in a simple wood frame with cut-stone lintel and sill. The entry is off-center on the left side and has a paneled door with transom. A cut-stone lintel lies overhead. The ell is 2 stories with a pitched roof. Penetration is symmetrical with 12 x 12 and 12 x 8 sash; each with cut-stone lintel and sill. Attached to the south side of the ell is a 1 story masonry addition with pitched roof and 2 x 2 sash.

Example of an early 19th century dwelling with much of its original integrity intact. This is a typical transitional Federal/Greek Revival period dwelling. The elliptical window is a Federal period vestige, the pedimented front, "L" shape plan and block lintels are Greek Revival details. This house is one of a dozen or more early 19th century, masonry houses along this street. Compare with others at 860, 881, 992, and 1021 Windsor Avenue.


This house was built by Giles Barber about 1825. Brick came from the brick-yards located along the east side of Windsor Avenue.

Stiles: Vol. II, page 53  
1869 Map  
Town of Windsor Assessor's Office

Michael K. O'Leary  
East (front)  
CHC, Sheet #22  
Spring, 1981

Preston Maynard  
Planning Consultant, Town of Windsor  
275 Broad Street, Windsor, CT 06095

None known  
Highways  
Private  
Revel  
Deterioration  
Zoning  
Development



WINDSOR - 11185 37 - BACK

(OVER)