

Photo 2. View from northwest showing main entrance facade facing west.

JUN 21 1976

NOV 7 1976



Photo 3. View of main facade from southwest.

NOV 7 1976 JUN 2 1 1976



Photo 4. North facade, with side of rear service ell at left.

Frankfort.

NOV 7 1976 JUN 21 1976



Photo 5. South facade.

Frankfort.

JUN 21 1976



Photo 6. Rear (east) facade, showing double gallery (one section now enclosed to accommodate a bathroom) and enclosed outside stairway.



Photo 7. Central hall from front entrance. Note plaster cornice in foreground, frescoed ceiling at rear. Stairhall arch can barely be glimpsed at right beyond transverse arch.



Photo 8. View through narrow door from front hall into northwest library showing portion of elaborate plasterwork on ceiling.



Photo 9. Stairhall, with side (south) entrance of mear. Note fine frosted and etched glass panels, and frescoed undersurface of stairs.



Frankfort. Photo 10. Former servants' quarters from south.

NOV 7 1976 21 1976



Photo 11. Former servants^t quarters from southwest, showing stable-barn at far right, open farmland beyond at left.

JUN 21 1976

NOV 7 1976



Frankfort. Photo 12. Stable-barn from southwest.

NOV 7 1976 JUN 2 1 1976