



PLAINFIELD WOOLEN COMPANY MILL
Central Village (Plainfield), CT

HRC Photo, 10/84

Negative filed with Conn.

Hist. Comm., Hartford

South and east elevations; main
entrance near corner, view west

1



NO
PARKING

PLAINFIELD WOOLEN COMPANY MILL
Central Village (Plainfield), CT

HRC Photo, 10/84

Negative filed with Conn.

Hist. Comm., Hartford

Detail, main entrance, view
southwest



PLAINFIELD WOOLEN COMPANY MILL
Central Village (Plainfield), CT

HRC Photo, 10/84

Negative filed with Conn.

Hist. Comm., Hartford

South elevation, ell; boiler
house on left, view northwest

3



PLAINFIELD WOOLEN COMPANY MILL
Central Village (Plainfield), CT

HRC Photo, 10/84

Negative filed with Conn.

Hist. Comm., Hartford

East and north elevations,
view south



PLAINFIELD WOOLEN COMPANY MILL
Central Village (Plainfield), CT

HRC Photo, 10/84

Negative filed with Conn.

Hist. Comm., Hartford

Rear elevation, showing attached
sheds, etc.; gable of dye house
visible, view southeast # 5



PLAINFIELD WOOLEN COMPANY MILL
Central Village (Plainfield), CT

HRC Photo, 10/84

Negative filed with Conn.

Hist. Comm., Hartford

Dyehouse, west elevation,
view east



PLAINFIELD WOOLEN COMPANY MILL
Central Village (Plainfield), CT

HRC Photo, 10/84

Negative filed with Conn.
Hist. Comm., Hartford

Tailrace arches at corner between
mill and ell, view east

7



PLAINFIELD WOOLEN COMPANY MILL
Central Village (Plainfield), CT

HRC Photo, 10/84

Negative filed with Conn.

Hist. Comm., Hartford

Typical interior, main mill,
second floor, view northwest



PLAINFIELD WOOLEN COMPANY MILL
Central Village (Plainfield), CT

HRC Photo, 10/84

Negative filed with Conn.
Hist. Comm., Hartford

Detail of monitor framing, top
floor, main mill

9



PLAINFIELD WOOLEN COMPANY MILL
Central Village (Plainfield), CT


HRC Photo, 10/84

Negative filed with Conn.

Hist. Comm., Hartford

Storehouse southeast of mill,
view southeast

10



PLAINFIELD WOOLEN COMPANY MILL
Central Village (Plainfield), CT

Negative from QVCC Library,
Danielson, Connecticut

Interior, floor below monitor,
weave room workers and looms,

c.1910

11