



PROPERTY OF THE NATIONAL REGISTER

Harwelden
Tulsa, OK SEP 12 1977
Gary Sparks - 1977
A&HC 2210 S Main Tulsa OK
#1 2 1/2 Front from ESE

TULSA CO.

FEB 8 1978



PROPERTY OF THE NATIONAL REGISTER

Harwelden

Tulsa, OK

SEP 12 1977

Gary Sparks - 1977

MR&HC 2210 S Main Tulsa OK

#2 ^{OK} Back from W

TULSA CO.

FEB 8 1978



Detail of front door to Harwelden.

Harwelden

Tulsa, OK

Gary Sparks - 1977

A&HC 2210 S Main Tulsa OK

FEB 8 1978

* 39/6
SEP 12 1977

TULSA CO.

PROPERTY OF THE NATIONAL REGISTER



Detail of lighting fixture at Main Entrance: 1 of a pair of bracket lanterns, triangular as per special design, rusty iron and brass.

TULSA CO.

Harwelden

Tulsa, OK

Gary Sparks - 1977

A&HC 2210 S Main Tulsa OK

#4916

FEB 8 1978 SEP 12 1977

PROPERTY OF THE NATIONAL REGISTER



Detail of wrought iron gate at Main Hall entrance.

FEB 8 1978

Harwelden - Tulsa OK

Gary Sparks - 1977

A&HC - 2210 S Main

#5 9/16 SEP-12-1977

Tulsa Co.

PROPERTY OF THE NATIONAL REGISTER



Detail of ornamentation over Main Entrance to Harwelden.

FEB 8 1978

Harwelden - Tulsa OK

Gary Sparks - 1977

A&HC - 2210 S Main

#6 216 SEP 12 1977

TULSA CO.

PROPERTY OF THE NATIONAL REGISTER



Newel post of Main staircase.

Tulsa Co.

Harwelden - Tulsa OK

Gary Sparks - 1977

A&HC - 2210 S Main

#7 of 16 SEP 12 1977

FEB 8 1978

PROPERTY OF THE NATIONAL REGISTER



Harwelden - Tulsa OK
Gary Sparks - 1977
A&HC - 2210 S Main
#8 216 SEP 12 1977

FEB 8 1978

View of living room to left of entrance from Main Hall looking into sunroom (door to left) and sun porch (door to right). With the exception of the rug in the living room, all furnishings are not originals.

Tulsa Co.

PROPERTY OF THE NATIONAL REGISTER



Detail of mantle in sun room. Mirror is an original furnishing.

Tulsa Co.

Harwelden - Tulsa OK

Gary Sparks - 1977

A&HC - 2210 S Main

#9 of 16 SEP 12 1977

FEB 8 1978

PROPERTY OF THE NATIONAL REGISTER



Main staircase. Iron and brass lantern 10' overall is original fixture.

Barely visible through banister is a Newcastle bench with red velvet cushion. Original furnishing.

Tulsa Co.

FEB 8 1978

Harwelden - Tulsa OK
Gary Sparks - 1977
A&HC - 2210 S Main
#10 of 16

SEP 12 1977

PROPERTY OF THE NATIONAL REGISTER



Harwelden - Tulsa OK

Gary Sparks - 1977

A&HC - 2210 S Main


#11 of 16 SEP 12 1977

FEB 8 1978

Detail showing family crest over outside door to library.

Tulsa Co.

PROPERTY OF THE NATIONAL REGISTER



Detail of slate roof.

Harwelden - Tulsa OK

Gary Sparks - 1977

A&HC - 2210 S Main

#12916 SEP 12 1977

FEB 8 1978

Tulsa CO.

PROPERTY OF THE NATIONAL REGISTER



View of dining room from living room entrance showing mantle piece of fireplace. Mantle contains 1 of 2 safes located in Harwelden.

Harwelden - Tulsa OK
Gary Sparks - 1977
A&HC - 2210 S Main

#13 8/6 SEP 12 1977

FEB 8 1978

Tulsa CO.

PROPERTY OF THE NATIONAL REGISTER



Harwelden -Tulsa OK
Gary Sparks - 1977
A&HC - 2210 S. Main
#17916 SEP 12 1977

View of sun porch. Curtains hang from specially designed wrought iron fixtures and brackets.
Iron furniture and pendant round lighting fixture are original furnishings.

TULSA CO.
FEB 8 1978

PROPERTY OF THE NATIONAL REGISTER



Harwelden - Tulsa OK

Gary Sparks - 1977

A&HC - 2210 S Main

#15 of 16

SEP 12 1977

FEB 8 1978

View of breakfast room from dining room. Shown is original pendant lighting fixture, pewter finish with hexagon shade. Also shown are 2 of 3 pairs of sash curtains of silk weave casement cloth finished with embroidery stitched hems.

Tulsa Co.

PROPERTY OF THE NATIONAL REGISTER



Detail of wall bracket in sunroom. An original fixture, it is made of wrought iron and brass and is 1 of a pair on either side of the doorway, entrance from Main Hall.

TULSA CO.

FEB 8 1978

Harwelden - Tulsa OK

Gary Sparks - 1977

A&HC - 2210 S Main

#16 9/6

SEP 12 1977

PROPERTY OF THE NATIONAL REGISTER