



UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY

RECEIVED MAR 25 1976

DATE ENTERED

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Jack Thomas House

AND/OR COMMON

The Gardner Place

2 LOCATION

CITY, TOWN

Leitchfield

___ VICINITY OF

COUNTY

Grayson

STATE

Kentucky

3 PHOTO REFERENCE

PHOTO CREDIT William J. Hughes

DATE OF PHOTO 1971

NEGATIVE FILED AT The Leitchfield Gazette

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO. 1 of 3

View of the north front of the house from the northwest. The openings were lengthened, hoodmolds applied, the cornice raised and bracketed, and the castiron porch and fence added in the last quarter of the 19th century.



UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM**

FOR NPS USE ONLY
RECEIVED MAR 23 1976
DATE ENTERED APR 21 1976

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Jack Thomas House

AND/OR COMMON

The Gardner Place

2 LOCATION

CITY, TOWN

___ VICINITY OF

COUNTY

STATE

Leitchfield

Grayson

Kentucky

3 PHOTO REFERENCE

PHOTO CREDIT

Mrs. Ruby T. Jones

DATE OF PHOTO

February 1976

NEGATIVE FILED AT 109 North English Street, Leitchfield, Kentucky.

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO. 2 of 3

View from the southwest showing the main block at left with the bricked-up round-arched door at the rear of the central hall, and the two-story porch with enclosed staircase probably added when the house was altered in the late 19th century.



UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

RECEIVED MAR 23 1976

DATE ENTERED APR 21 1976

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*
TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Jack Thomas House

AND/OR COMMON

The Gardner Place

2 LOCATION

CITY, TOWN

Leitchfield

____ VICINITY OF

COUNTY

Grayson

STATE

Kentucky

3 PHOTO REFERENCE

PHOTO CREDIT

Mrs. Ruby T. Jones

DATE OF PHOTO February 1976

NEGATIVE FILED AT Kentucky Heritage Commission

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO. 3

View from the southeast. The brick one-story wing at left (with later frame addition above and recent additions in foreground) is thought to be the oldest part of the house. It originally faced the old road that ran along a cliff off the picture to the right. The present rear wall of the ell (at left) originally had a center chimney flanked by small "lookout windows" in the loft, and perhaps other openings now bricked up.



Jack Thomas House, Leitchfield,
Grayson County, Kentucky
Walter E. Langsam, Kentucky
Heritage Commission, February 1976
(from color slide)

Photo 1. Center portion of north
facade showing detail of Victorian
porch and trim; remnants of
brickwork of original Palladian
windows.



Jack Thomas House, Leitchfield,
Grayson County, Kentucky
Walter E. Langsam, Kentucky
Heritage Commission, February 1976
(from color slide)

Photo 2. North facade from
northwest.