



The Green Onion

Colbert County near Leighton, Alabama

Robert Gamble, 12/83

Gamble files (AHC)

Front facing SW

Photo number: 1



The Green Onion

Colbert County near Leighton, Alabama

Robert Gamble, 12/83

Gamble files (AHC)

Side facing SE

Photo number: 2



The Green Onion

Colbert County near Leighton, Alabama

Robert Gamble, 12/83

Gamble files (AHC)

Side facing SW

Photo number: 3



The Green Onion

Colbert County near Leighton, Alabama

Robert Gamble, 12/83

Gamble files (AHC)

Detail of brickwork

Photo number: 4



The Green Onion

Colbert County near Leighton, Alabama

Robert Gamble, 8/85

Gamble files (AHC)

Detail of foundation wall showing row of decorative brick headers

Photo number: 5



The Green Onion

Colbert County near Leighton, Alabama

Robert Gamble, 8/85

Gamble files (AHC)

Detail of interior stairs between first and second floors

Photo number: 6



The Green Onion

Colbert County near Leighton, Alabama

Robert Gamble, 8/85

Gamble files (AHC)

First floor showing cross and Bible door,  
original plaster and exposed brick where  
wainscot was once attached

Photo number: 7



The Green Onion

Colbert County near Leighton, Alabama

Robert Gamble, 8/85

Gamble files (AHC)

First floor showing original baseboard, window surrounds, plaster, etc. Note absence of wainscot and chair rail

Photo number: 8



The Green Onion

Colbert County near Leighton, Alabama

Robert Gamble, 8/85

Gamble files (AHC)

Second floor interior showing original beaded  
paneling

Photo number: 9



The Green Onion

Colbert County near Leighton, Alabama

Robert Gamble, 8/85

Gamble files (AHC)

First floor interior showing remnants of original baseboard and chair rail

Photo number: 10



The Green Onion

Colbert County near Leighton, Alabama

Robert Gamble, 8/85

Gamble files (AHC)

Second floor fireplace opening

Photo number: 11