

INDIVIDUAL DATA SHEET

Property Name Shores Warehouse Property Owner Don Shores
Location Main Street, Cave Springs (Hwy. 112) Address Cave Springs, AR 72718
Construction Date c. 1911 Survey No. 2127

DESCRIPTION

The Shores Warehouse is a two-story commercial building facing east on the Main Street of Cave Springs. Concrete block stanchions (or mullions) divide the forty foot wide street facade into six plate glass bays. The end bays have been sealed in recent years with masonry infill. An entry door is located in the second bay from the left. A metal awning shelters the entire width of the first floor above which rises the concrete block second floor facade, broken only by four one-over-one double-hung windows. The front is topped by a pressed metal dentilated classical cornice. The concrete blocks of the front and south facades are shaped, simulating rusticated stone. The original integrity of this commercial front is only affected by the masonry infill of the two end bays.

STATEMENT OF SIGNIFICANCE

Criterion: CArea of significance: Architecture

The Shores Warehouse, facing east on Main Street of Cave springs, was built c. 1911. By virtue of its dignified symmetry, its two-story facade unblemished by insensitive signage or modification, this building brings a high degree of architectural distinction to this small town Main Street. Although it was built as a retail store and has served as such in the past, it is presently used for warehouse storage. The building is significant not only as an architectural representative of a small-town early twentieth century commercial district, but also as a fine example of the group of concrete block buildings which were constructed in Benton County during this period.

Acreage less than 1 acreVerbal Boundary Description Lots 12 and 13, Block 9Quadrangle Name Bentonville South, Ark. Quadrangle Scale 1:24000UTM Reference: Zone 15 Easting 389330 Northing 4013540

12/4/87

United States Department of the Interior
National Park ServiceNational Register of Historic Places
Continuation Sheet

Section number _____ Page _____

Multiple Resource Area
Thematic GroupName Benton County MRA
State Benton County, ARKANSAS

Nomination/Type of Review

Date/Signature

81. Rocky Branch School

Entered in the
National RegisterKeeper Shelous Byers 3/25/88

Attest _____

82. Rogers City Hall

Entered in the
National RegisterKeeper Shelous Byers 1/28/88

Attest _____

83. Rogers Post Office Building

Entered in the
National RegisterKeeper Shelous Byers 1/28/88

Attest _____

84. Roy's Office Supply Building

Entered in the
National RegisterKeeper Shelous Byers 1/28/88

Attest _____

85. Sellers Farm

Entered in the
National RegisterKeeper Shelous Byers 1/28/88

Attest _____

86. Shady Grove School

Entered in the
National RegisterKeeper Shelous Byers 1/28/88

Attest _____

87. Shiloh House

Entered in the
National RegisterKeeper Shelous Byers 1/28/88

Attest _____

88. Shores Warehouse

Entered in the
National RegisterKeeper Shelous Byers 1/28/88

Attest _____

89. Siloam Springs Train Station

Entered in the
National RegisterKeeper Shelous Byers 1/28/88

Attest _____

90. Spavinaw Creek Bridge

Entered in the
National RegisterKeeper Shelous Byers 1/28/88

Attest _____

87002374

NATIONAL REGISTER OF HISTORIC PLACES
EVALUATION/RETURN SHEET

Shores Warehouse (Benton County MRA)
Benton County
ARKANSAS

DEC 14 1987

Working No. _____

Fed. Reg. Date: 2/7/89

Date Due: 1/14/88 - 1/28/88

Action: ACCEPT 1-28-88

RETURN

REJECT

Federal Agency: _____

- ☐ resubmission
☐ nomination by person or local government
☐ owner objection
☐ appeal

Entered in the
National Register

Substantive Review: ☐ sample ☐ request ☐ appeal ☐ NR decision

Reviewer's comments:

Recom./Criteria _____

Reviewer _____

Discipline _____

Date _____

_____ see continuation sheet

Nomination returned for: _____ technical corrections cited below
_____ substantive reasons discussed below

1. Name

2. Location

3. Classification

Category	Ownership	Status	Present Use
	Public Acquisition	Accessible	

4. Owner of Property

5. Location of Legal Description

6. Representation in Existing Surveys

Has this property been determined eligible? ☐ yes ☐ no

7. Description

Condition	Check one	Check one
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered
<input type="checkbox"/> good	<input type="checkbox"/> ruins	<input type="checkbox"/> altered
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed	<input type="checkbox"/> original site
		<input type="checkbox"/> moved date _____

Describe the present and original (if known) physical appearance

- ☐ summary paragraph
☐ completeness
☐ clarity
☐ alterations/integrity
☐ dates
☐ boundary selection

8. Significance

Period _____ Areas of Significance—Check and justify below

Specific dates _____

Builder/Architect _____

Statement of Significance (*in one paragraph*)

- ☐ summary paragraph
- ☐ completeness
- ☐ clarity
- ☐ applicable criteria
- ☐ justification of areas checked
- ☐ relating significance to the resource
- ☐ context
- ☐ relationship of integrity to significance
- ☐ justification of exception
- ☐ other

9. Major Bibliographical References

10. Geographical Data

Acreage of nominated property _____

Quadrangle name _____

UTM References _____

Verbal boundary description and justification _____

11. Form Prepared By

12. State Historic Preservation Officer Certification

The evaluated significance of this property within the state is:

____ national ____ state ____ local

State Historic Preservation Officer signature

title _____ date _____

13. Other

- ☐ Maps
- ☐ Photographs
- ☐ Other

Questions concerning this nomination may be directed to _____

Signed _____ Date _____ Phone: _____



No. 59
SHORES WAREHOUSE - 2127

CAVE SPRINGS

BENTON CO. MRA

PHOTO'D BY BENTON CO. SURVEY STAFF, 1984

NEGATIVES on FILE at AHPP

Please refer to the map in the
Multiple Property Cover Sheet
for this property

Multiple Property Cover Sheet Reference Number: 64000022