



601 N. Park Ave.
Montrose, CO 81401

U.S. Bureau of Reclamation Office Building (District)
(Uncompahgre Project)

Photographer unknown, 1906

Negative at U.S. Bureau of Reclamation,
upper Colorado Regional office, Salt
Lake City, UT 84147

View of building 1 from Park Ave,
looking virtually due north.

Photograph 1 on sketch map.



601 N. Park Ave.

Montrose, CO 81401

U.S. Bureau of Reclamation Office Building (Part of District)
(Uncompahgre Project)

Photographer: David Gates, 1991

Negative at U.S. Bureau of Reclamation office
Grand Junction, CO 81506

Photograph 2 on sketch map



UNCOMPAHGRE VALLEY WATER USERS

6

1

601 N. Park Ave.

Montrose, CO 81401

U.S. Bureau of Reclamation Office Building (District)
(Uncompahgre Project)

Photographer: Dave Gates, 1991

Negative at U.S. Bureau of Reclamation office
Grand Junction, CO 81506

View of building 1 from Park Ave,
looking northeast.

Photograph 3 on sketch map.



UNCOMPAHGRE VALLEY WATER USERS



601 N. Park Ave.
Montrose, CO 81401

U.S. Bureau of Reclamation office Building (District)
(Uncompahgre Project)

Photographer: David Gates, 1991

Negative at U.S. Bureau of Reclamation office
Grand Junction, CO 81506

View of building 1 from Park Ave.,
looking east.

Photograph 4 on sketch map.



601 N. Park Ave.
Montrose, CO 81401

Support buildings at U.S. Bureau of Reclamation
District Complex (Uncompahgre Project)

Photographer: David Gates, 1991

Negative at U.S. Bureau of Reclamation office
Grand Junction, CO 81506

View of buildings 2, 3, 4 and part of 5
looking northwest from the roof of the
main office building (building 1).

Photograph 5 on sketch map.



601 N. Park Ave.

Montrose, CO 81401

Support buildings at Bureau of Reclamation
District Complex (Uncompahgre Project)

Photographer: David Gates, 1991

Negative at U.S. Bureau of Reclamation Office
Grand Junction, CO 81506

View of buildings 5, 6, 7, 8, 9, 11, and part of 4
looking north from the 'roof' of the main
office building (building 1).

Photograph 6 on sketch map.



601 N. Park Ave.

Montrose, CO 81401

Support buildings at Bureau of Reclamation
District Complex (uncompahgre Project)

Photographer: David Gates, 1991

Negative at U.S. Bureau of Reclamation office
Grand Junction, CO 81506

View of building 10 and parts of building 9 and 11,
looking northeast from the roof of the main
office building (building 1).

Photograph 7 on sketch map.



601 N. Park Ave.
Montrase, CO 81401

U.S. Bureau of Reclamation
Office Building (Uncompahgre
Project) Interior View

Photographer Unknown, 1906 or 1907

Negative at U.S. Bureau of
Reclamation, Upper Colorado
Regional Office, Salt Lake
City, UT 84147

Interior of building 1,
probably on first floor.



601 N. Park Ave.

Montrose, CO 81401

U.S. Bureau of Reclamation
Office Building (Uncompahgre
Project) Interior View

Photographer Unknown, 1906

Negative at U.S. Bureau of
Reclamation, upper Colorado
Regional Office, Salt Lake
City, UT 84147

Interior of building 1,
probably on first floor.



601 N. Park Ave.

Montrose, CO 81401

U.S. Bureau of Reclamation Office Building
(Uncompahgre Project)

Photographer: David Gates, 1991

Negative at U.S. Bureau of Reclamation,
Grand Junction, CO 81506

Interior of building I, door handle on
first floor.



601 N. Park Ave.

Montrose, CO 81401

U.S. Bureau of Reclamation office Building
(Uncompahgre Project)

Photographer: David Gates, 1991

Negative at U.S. Bureau of Reclamation
Grand Junction, CO 81506

Interior of building 1, door frame
on first floor.



thank
you

for not smoking

601 N. Park Ave.

Montrose, CO 81401

U.S. Bureau of Reclamation Office Building
(Uncompagre Project)

Photographer: David Gates, 1991

Negative at U.S. Bureau of Reclamation,
Upper Colorado Regional Office, Salt Lake City,
UT 84147

Interior of building 1, staircase from first to
second floor.