Property Type:

Utah State Historical Society

Historic Preservation Research Office

SIGN, SITE # 7

Structure/Site Information Form

Street Address:	UTM: 12/356250/4236900				
Name of Structure:			T.	R.	S.
Present Owner:∕ Armond Monfredi, et		UX LESS THAN O			ine Alre
Owner Address:	Beaver, Utah 84713				
Year Built(Tax Record) Legal Description		ve Age: f Building:		Tax # : B-19-	-В
PLAT A BLK	6 NORTHWEST	QUARTER DI	Lot 3		1
					١
 Original Owner: Jose	ph Huntington) + · · ·	Construction	n Date: 1878	Demolitio	n Date:
Original Use: Residence		Presont Use: Residence			
Building Condition:	Integrity:	Preliminary Eval	uation:	Final Registe	r Status:
Excellent Gite Good Ruins Deteriorated	Addition made, Ø Unaltered Minor Alterations Major Alterations	but within the ☑ Significant □ Contributory □ Not Contributory	historic p Not of the Historic Period	eriod National Landm National Regist State Register	
Photography: Date of Slides:		Slide No.:	Date of Phot	ographs:	Photo No.:
Views: 🗆 Fr	Views: 🗆 Front 🗀 Side 🗆 Rear 🗆 Other		vs: 🗆 Front 🗆 Sid	le 🗆 Rear 🗔 Other	
Plat Records / Map Image: Control of the second	Sanborn Maps City Directories Biographical Encyclopedias Obiturary Index County & City Histories	 Newspapers Utah State Histori Personal Interview LDS Church Arch LDS Genealogica 	ws ives	 U of U Library BYU Library USU Library SLC Library V Other Fieldward 	vork

Bibliographical References (books, articles, records, interviews, old photographs and maps, etc.):

Two 1933 photos "Oral interview and tour of interior with tenant of the house, September 1978. Oral interview with Mr. Monfredi 5/26/79. Mrs. Louise Roberts interviewed 6/9/79 by Linda L. Bonar in Beaver.

STATUS/USE 2

DOCUMENTATION S

100000000000	Street Address:	215 South 2nd West	BV-04-32	
	Architect/Builder:	Probably Joseph Huntington		
	Duilding Materiala			

Building Type/Style:

Description of physical appearance & significant architectural features: (Include additions, alterations, anciliary structures, and landscaping if applicable)

All walls, interior and exterior, are about 20" thick. The south bay was added on to the original building. Pink rock lean-to on rear north section is rubble stone, south section is cut stone.

Out building, excellent shape structurally. The first three quoins from the ground up are black rock (basalt) on each of the four corners. The next four are pink rock (tuff).

140.00

Statement of Historical Significance:

Construction Date:

The house is $g_{1,g_{W1}} + g_{1,c_{GW}} + g_{1,c_$



