



FILION
Jewelers

WATCHES

Te

U.S. Post Office, Port Angeles, Washington
Photographer: Kristine Bak
Date of Photograph: August 1980
Location of Negative: GSA Center, Auburn, WA
Front Facade
Photograph #1 of 5



U.S. Post Office, Port Angeles, Washington

Photographer: Kristine Bak

Date of Photograph: August 1980

Location of Negative: GSA Center, Auburn, WA

Rear Facade

Photograph #2 of 5



U.S. Post Office, Port Angeles, Washington

Photographer: Kristine Bak

Date of Photograph: August 1980

Location of Negative: GSA Center, Auburn, WA

Marine setting of downtown Port Angeles

with U.S. Post Office in foreground

Photograph #3 of 5



U.S. Post Office, Port Angeles, Washington

Photographer: Unknown

Date of Photograph: 1950's

Location of Negative: GSA Center, Auburn, WA

Front Facade

Photograph #4 of 5



U.S. Post Office, Port Angeles, Washington

Photographer: Unknown

Date of Photograph: 1950's

Location of Negative: GSA Center, Auburn, WA
Rear Facade

Photograph #5 of 5



PORT ANGELES
98362

U.S. Post Office, Port Angeles, Washington

Photographer: Kristine Bak

Date of Photograph: August 1980

Location of Negative: GSA Center, Auburn, WA

Main Entrance surrounded by heavy, rusticated Wilkeson sandstone columns and eagle surmounted entablature.

Photograph #1 of 9



U.S. Post Office, Port Angeles, Washington

Photographer: Kristine Bak

Date of Photograph: August 1980

Location of Negative: GSA Center, Auburn, WA
Main Entrance fan light.

Photograph #2 of 9

A W MELLON
SECRETARY OF THE TREASURY
JAMES A WETMORE
ACTING SUPERVISING ARCHITECT
1931

U.S. Post Office, Port Angeles, Washington

Photographer: Kristine Bak

Date of Photograph: August 1980

Location of Negative: GSA Center, Auburn, WA
Cornerstone

Photograph #3 of 9



U.S. Post Office, Port Angeles, Washington

Photographer: Kristine Bak

Date of Photograph: August 1980

Location of Negative: GSA Center, Auburn, WA

First lobby area looking easterly.

Photograph #4 of 9



U.S. Post Office, Port Angeles, Washington

Photographer: Kristine Bak

Date of Photograph: August 1980

Location of Negative: GSA Center, Auburn, WA
Cast iron ornamental lamp standard at building front.

Photograph #5 of 9



U.S. Post Office, Port Angeles, Washington

Photographer: Kristine Bak

Date of Photograph: August 1980

Location of Negative: GSA Center, Auburn, WA

First floor lobby looking westerly

Photograph #6 of 9



U.S. Post Office, Port Angeles, Washington

Photographer: Kristine Bak

Date of Photograph: August 1980

Location of Negative: GSA Center, Auburn, WA

Original light fixture, first floor lobby.

Photograph #7 of 9

211

BUREAU OF
INDIAN AFFAIRS

U.S. Post Office, Port Angeles, Washington

Photographer: Kristine Bak

Date of Photograph: August 1980

Location of Negative: GSA Center, Auburn, WA

Chipped glass translucent window in second
floor office door.

Photograph #8 of 9



U.S. Post Office, Port Angeles, Washington

Photographer: Kristine Bak

Date of Photograph: August 1980

Location of Negative: GSA Center, Auburn, WA
Second floor corridor looking easterly.

Photograph #9 of 9