

Cains Coffee Company Building
Oklahoma City, Oklahoma

View from the S.W., looking at the front (S.) side, and the west end.

DEC 2 2 1981 FEB 4 1982

RAIL ROAD
CROSSING
TRACKS

Cains Coffee Company Building
Oklahoma City, Oklahoma
View from the S.E., looking at the east end and the front side. Notice the close proximity to the tracks.

DEC 22 1981

FEB 4 1982

Cains Coffee Company Building
Oklahoma City, Oklahoma
View from the N.E., looking at the back (N.) side, and the E. end. Notice the attached lean-to garage.

FEB 4 1982 DEC 2 2 1981

FEB 4 1982

Cains Coffee Company Building
Oklahoma City, Oklahoma
View from the S.E., looking at the E. end.
Notice the side tracks which once were used
for loading and unloading. Also notice the
windows which were remodelled with new glass

Cains Coffee Company Building
Oklahoma City, Oklahoma
View from the W., looking at the W. end of the lean-to garage.

FEB 4 1982

DEC 22 1981

Cains Coffee Company Building
Oklahoma City, Oklahoma
View from the E., looking at the E. end of the lean-to garage.

FEB 4 1982 DEC 22 1981

SOUTHWEST CONSTRUCTION
NEWS SERV.

Cains Coffee Company Building
Oklahoma City, Oklahoma
View of the stairway in the two-story entryway.

DEC 22 1981 FEB 4 1982

Cains Coffee Company Building
Oklahoma City, Oklahoma
View of the partitions on the remodelled first level.

FEB 4 1982

DEC 2 2 1981

Cains Coffee Company Building
Oklahoma City, Oklahoma
View of a typical upper floor

FEB 4 1982

DEC 2 2 1981



Cains Coffee Company Building
Oklahoma City, Oklahoma
View of the glazed tile on the S. side.

FEB 4 1982

DEC 2 2 1981

Cains Coffee Company Building
Oklahoma City, Oklahoma
View of the rubble on the third floor.

DEC 22 1981 FEB 4 1982