



Thomas Richards House
Cecil County, Maryland
Ronald W. Edwards, 1977
Rising Sun, Md

CE-230

DEC

DOE

19

Wall showing bake oven (to be restored)
adjacent to cooking fireplace stone section.

1920



Something went wrong while we were encoding this page.
Please check the log file to find out the details.

Thomas Richards House
Cecil County, Maryland
Ronald W. Edwards, 1977
Rising Sun, Md.
Small Fireplace in Bedroom of Stone Section

CE-230

DOE

DEC 19 1979

2 of 20



Thomas Richards House
Cecil County, Maryland
Ronald W. Edwards, 1977
Rising Sun, Md.
South Elevation

CE-230

39/20

DOE
DEC 19 1979



CE-230

Thomas Richards House
Cecil County, Maryland
Ronald W. Edwards, 1977
Rising Sun, Md.
House from northwest

DOE

DEC 19 1979

#4/8/20



Thomas Richards house

CE-230

Cecil County, Maryland

Ronald W. Edwards, 1977

Rising Sun, Md.

House viewed from the north

#59/20

DEC

DOE
19 1979



Thomas Richards house
Cecil County, Maryland
Ronald W. Edwards, 1977
Rising Sun, Mc.

CE-230

DEC 1 1977
E

large kitchen (cooking) fireplace in stone
section, mantel shelf 8' long, fireplace
opening 5'4" wide by 4'7" high

#6 of 20



Thomas Richards house

CE-230

Cecil County, Maryland

Ronald W. Edwards, 1977

70/20

Rising Sun, Maryland

beaded paneling of closet and ceiling in *POE*

bedroom of stone section

DEC 19 1979



Thomas Richards House
Cecil County, Maryland
Ronald W. Edwards, 1977
Rising Sun, Md.
Barn, north elevation

CE-230

8 of 20

DOE
DEC 19 1977



Thomas Richards House
Cecil County, Maryland
Ronald W. Edwards, 1977
Rising Sun, Md.
north elevation

CE-230

9420

DOE

DEC 19 1975



Thomas Richards House
Cecil County, Maryland
Ronald W. Edwards, 1977
Rising Sun, Maryland
from the southeast

CE-230

#10 of 20

DEC

19

1979

POE



Thomas Richards House

CE-230

Cecil County, Maryland

Ronald W. Edwards, 1977

Rising Sun, Md.

Barn, viewed from northeast

DOE

DEC 19 1979

#11/20



Thomas Richards House
Cecil County, Maryland
Ronald W. Edwards, 1977
Rising Sun, Md.


CE-230

DOE

DEC 19 1978

Beaded paneling in downstairs room of stone section, east wall entrance (3 stone steps down) to brick stone basement (now modern kit.)

#124/20



Thomas Richards house CE-230

Cecil County, Maryland

Ronald W. Edwards, 1977

Rising Sun, Maryland

Door latch of front door of stone section.

DOE
DEC 19 1979

#139/20



Thomas <u>Richard</u> house	CE-230
Cecil County, Maryland	
Ronald W. Edwards, 1977	OCT 16 1979
Rising Sun, Maryland	
Chair railing and door moulding of living room, room, brick section, west wall, note <i>DOES</i> symmetry of doors	DEC 19 1979

#14 of 20



Thomas Richards house

CE-230

Cecil County, Maryland

Ronald W. Edwards, 1977

Rising Sun, Maryland

Front door of stone section

9
POE

OCT 16 1979
#15920



Something went wrong while we were encoding this page.
Please check the log file to find out the details.

Thomas Richards house

CE-230

Cecil County, Maryland

Ronald W. Edwards, 1977


OCT 16 1979

Rising Sun, Maryland

Window moulding in living room, brick section

#16 of 20

DOE
DEC 19 1979



Thomas Richards house

CE-230

Cecil County, Maryland

Ronald W. Edwards, 1977

OCT 16 1979

Rising Sun, Maryland

Detail of fireplace mantel

side (chimney)

cupboard and chair railing

in Library of *ACE*

brick section.

#179/20

DEC 19 1979



Thomas Richards house

CE-230

Cecil County, Maryland

Ronald W. Edwards, 1977

OCT 16 1979

Rising Sun, Maryland

Beaded paneling of stairway, stone section

18420

DOE

DEC 19 1979



Thomas Richards house

CE-230

Cecil County, Maryland

Ronald W. Edwards, 1977

OCT 16 1979

Rising Sun, Maryland

detail of living room mantel and cupboard

brick section

#194/20

DOE
DEC 19 1979



Thomas Richards house

CE-230

Cecil County, Maryland

OCT 16 1979

Ronald W. Edwards, 1977

Fireplace & mantel in living room of brick
seciton east gable/

DOE

DEC 19 1979

20720
~~# *[scribble]*~~