

Name: Poplar Level

Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: M.R. Loockerman, copied by T.C. Adams Date of Photograph: 1938, copied 1979 Location of Negative: private collection

Description: south (front) elevation

Photograph Number: 1 of 23




Name: Poplar Level

Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: south (front) elevation

Photograph Number: 2 of 23





```
Name: Poplar Level
```

Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Descripton: three-quarter view of south and east elevation

Photograph Number: 3 of 23





Name: Poplar Level

Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: three-quarter view of south and west elevation

Photograph Number: 4 of 23





- Name: Poplar Level
- Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection
- Description: detail of west section of south elevation

Photograph Number: 5 of 23





Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: detail of south entrance

Photograph Number: 6 of 23



```
Name: Poplar Level
```

Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: west elevation

Photograph Number: 7 of 23



- Name: Poplar Level
- Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection
- Description: detail of formerly exposed brick chimney on west gable end

Photograph Number: 8 of 23





Location: roads 32 and 34 southwest of Greenwood Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Descripton: three-quarter view of north and west elevation

Photograph Number: 9 of 23



Name: Poplar Level

Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: three-quarter view of north and east elevation

Photograph Number: 10 of 23



- Name: Poplar Level
- Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection
- Description: detail of north entrance, west section

Photograph Number: 11 of 23




Name: Poplar Level

Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: M.R. Loockerman, copied by T.C. Adams Date of Photograph: 1938, copied 1979 Location of Negative: private collection

Description: detail of sitting room (east wall)

Photograph Number: 12 of 23





Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: detail interior side of entrance doorway on south elevation, three-bay section

Photograph Number: 14 of 23





Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: detail entrance hall stairway (east wall, three-bay section of house)

Photograph Number: 13 of 23



Name: Poplar Level

Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Descripton: detail of parlor mantelpiece (west wall, three-bay section)

Photograph Number: 15 of 23



Name: Poplar Level

Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: T. C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: detail of sitting room, late 18th century panelling (east wall, two-bay section)

Photograph Number: 16 of 23



Name: Poplar Level

Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: M.R. Loockerman, copied by T.C. Adams Date of Photograph: 1939, copied 1979 Location of Negative: private collection

-Description: north elevation

Photograph Number: 17 of 23





Location: roads 32 and 34 southwest of Greenwood, Sussex Couunty, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: west elevation of concrib (northeast of house)

Photograph Number: 18 of 23




Name: Poplar Level

Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: T. C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: south elevations of outbuildings, north of house (from left: corncrib, barn, machine, shed, barn)

Photograph Number: 19 of 23



Name: Poplar Level

Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: three-quarter view of south and east elevations of outbuildings, northwest of house (from left: machine sheds, pigpen, corncrib, barn)

Photograph Number: 20 of 23



Name: Poplar Level

Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: T. C. Adams Date of Photograph: 1980 Location of Negative: private collection

Descripton: three-quarter view of south and east elevations, machine shed, northwest of house

Photograph Number: 21 of 23





Name: Poplar Level

Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: three-quarter view of east and north elevation of chicken house, west of house

Photograph Number: 22 of 23



Name: Poplar Level

Location: roads 32 and 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: three-quarter view of east and north elevation of chicken and brooder house

Photograph Number: 23 of 23



Name: Middle Space

Location: northwest corner county roads 34 and 32, southwest of Greenwood, Sussex County, Delaware Photographer: unidentified; copied by T.C. Adams Date of Photograph: c. 1912, copied 1980 Location of Negative: private collection

Description: hand-colored photograph of farm c. 1912

Photograph Number: 1 of 18




Name: Middle Space

Location: northwest corner county roads 34 and 32, southwest of Greenwood, Sussex County, Delaware Photographer: M.R. Loockerman; copied by T.C. Adams Date of Photograph: 1941 Location of Negative: private collection

Description: south (front) elevation

Photograph Number: 2 of 18





Location: northwest corner county roads 34 and 32, southwest of Greenwood, Sussex County, Delawre Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Descripton: three-quarter view of property, south and east elevations


Photograph Number: 3 of 18





- Name: Middle Space
- Location: northwest corner county roads 34 and 32, southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection
- Description: south elevations, house and barn

Photograph Number: 4 of 18







Location: northwest corner county roads 34 and 32, southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: detail, south elevation, west (1870's) section

Photograph Number: 5 of 18






Location: northwest corner county roads 34 and 32, southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: detail, south entrance, colored transom lights

Photograph Number: 6 of 18






Location: northwest corner county roads 34 and 32, southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: detail, south elevation window

Photograph Number: 7 of 18





Location: northwest corner county roads, 34 and 32, southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: three-quarters view of south and east elevations

Photograph Number: 8 of 18





Name: Middle Space

Location: northwest corner county roads, 34 and 32, southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Descripton: east elevation

Photograph Number: 9 of 18





Location: northwest corner county roads 34 and 32, southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: north (rear) elevation

Photograph Number: 10 of 18





Location: northwest corner county roads 34 and 32, southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: west elevation

Photograph Number: 11 of 18



Name: Middle Space

Location: northwest corner county roads 34 and 32, southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: north wall of kitchen

Photograph Number: 12 of 18





Location: northwest corner county roads 34 and 32, southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: detail, west wall of sitting room

Photograph Number: 13 of 18





Name: Middle Space

Location: northwest corner county roads 34 and 32, southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: east and north elevations, dairy, north of house

Photograph Number: 14 of 18





Name: Middle Space

Location: northwest corner county roads 34 and 32, southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: Private collection

Descripton: south and east elevations of machine repair shop (left) and machine shed

Photograph Number: 15 of 18



Name: Middle Space

Location: northwest corner county roads 34 and 32, southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: south and west elevations of granary

Photograph Number: 16 of 18



Name: Middle Space

Location: northwest corner county roads 34 and 32, southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: main barn, west elevation

Photograph Number: 17 of 18





Name: Middle Space

Location: northwest corner county roads 34 and 32, southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: north elevations of outbuildings, (from left, main barn, granary, machine shop, machine shed)

Photograph Number: 18 of 18





Location: county road 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1978 Location of Negative: private collection

Description: south (front) elevation

Photograph Number: 1 of 19



Name: Locust Grove

Location: county road 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1978 Location of Negative: private collection

Description: detail, south entrance

Photograph Number: 2 of 19




Name: Locust Grove

Location: county road 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1979 Location of Negative: private collection

Descripton: detail, 9/6 sash window, south elevation

Photograph Number: 3 of 19






Location: county road 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1979 Location of Negative: private collection

Description: three-quarters view of south and east elevations

Photograph Number: 4 of 19





Location: county road 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1979 Location of Negative: private collection

Description: porch on east elevation

Photograph Number: 5 of 19






Location: county road 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1980 Location of Negative: private collection

Description: north (rear) elevation

Photograph Number: 6 of 19





Location: county road 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1978 Location of Negative: private collection

Description: detail, entrance on north elevation

Photograph Number: 7 of 19





Name: Locust Grove

Location: county road 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1979 Location of Negative: private collection

Description: detail, interior of south elevation entrance, brick section

Photograph Number: 8 of 19






Location: county road 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1979 Location of Negative: private collection

Descripton: detail, entrance hall stairway, brick section

Photograph Number: 9 of 19






- Name: Locust Grove
- Location: county road 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1979 Location of Negative: private collection
- Description: detail, parlor mantelpiece, west wall, brick section

Photograph Number: 10 of 19






Location: county road 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1978 Location of Negative: private collection

Description: detail, parlor window enframement, brick section

Photograph Number: 11 of 19






Location: county road 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1979 Location of Negative: private collection

Description: detail, hand-painted fireboard for parlor fireplace, photographed on grounds

Photograph Number: 12 of 19






Location: county road 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1978 Location of Negative: private collection

Description: detail, mantelpiece and hand-painted fireboard, second story, west wall, brick section

Photograph Number: 13 of 19




RICHARDS HISTORIC DISTRICT

Name: Locust Grove

Location: county road 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1978 Location of Negative: private collection

Description: detail, attic level, east brick gable end windows

Photograph Number: 14 of 19





Location: county road 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1978 Location of Negative: private collection

Descripton: south elevation of frame barn, north of house

Photograph Number: 15 of 19






Location: county road 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1978 Location of Negative: private collection

Description: east elevation of corncrib, north of house

Photograph Number: 16 of 19






Location: county road 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1978 Location of Negative: private collection

Description: east elevation of machine shed, north of house

Photograph Number: 17 of 19





Location: county road 34 southwest of Greenwood, Sussex County, Delaware Photographer: T.C. Adams Date of Photograph: 1979 Location of Negative: private collection

Description: detail, wrought iron entrance gate, family cemetary, northwest of house

Photograph Number: 18 of 19



RICHARDS HISTORIC DISTRICT

Name: Locust Grove

Location: county road 34 southwest of Greenwood Sussex County, Delaware Photographer: unidentified; copied by T.C. Adams Date of Photograph: c. 1916, copied 1979 Location of Negative: private collection

Description: M.R. Loockerman in front of south elevation of Locust Grove

Photograph Number: 19 of 19