



Liberty Hall

Camden, AL , Wilcox County

Marion Furman, 1983

Alabama Historical Commission

Rear Section: Dining room and
kitchen

1 of 12 photos



Liberty Hall

Camden, AL, Wilcox County

Marion Furman, 1983

Alabama Historical Commission

Window Detail

2 of 12 photos



Liberty Hall


Camden, AL, Wilcox County

Marion Furman, 1983

Alabama Historical Commission

Plaster Work Downstairs Hall

3 of 12 photos



Liberty Hall

Camden, AL, Wilcox County

Marion Furman, 1983

Alabama Historical Commission

Ceiling Plaster Moulding Parlor

4 of 12 photos



Liberty Hall

Camden, AL, Wilcox County

Marion Furman, 1983

Alabama Historical Commission

Doric Columns

5 of 12 photos



Liberty Hall

Camden, AL, Wilcox County

Marion Furman, 1983

Alabama Historical Commission

6 of 12 photos



Liberty Hall

Camden, AL, Wilcox County

Marion Furman, 1983

Alabama Historical Commission

Mantle Wood with Plaster

7 of 12 photos



Liberty Hall

Camden, AL, Wilcox County

Marion Furman, 1983

Alabama Historical Commission

Staircase from Downstairs Hall

8 of 12 photos



Liberty Hall

Camden, AL, Wilcox County

Marion Furman, 1983

Alabama Historical Commission

Downstairs Hallway - Plaster

Moulding - Stairway - Fanlight

9 of 12 photos



Liberty Hall

Camden, AL, Wilcox County

Marion Furman, 1983

Alabama Historical Commission

Left Parlor Mantel - Wood with
Plaster Ornamentation

10 of 12 photos



Liberty Hall

Camden, AL, Wilcox County

Marion Furman, 1983

Alabama Historical Commission

Plaster Medallion - Parlor

11 of 12 photos



Liberty Hall

Camden, AL, Wilcox County

Marion Furman, 1983

Alabama Historical Commission

12 of 12 photos