



Santa Rosa, California

#1 of 26

Photo taken by Don Silverek (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Front view



Sanoma County, Sonoma

Photo # 2 of 26

Photo taken by Don Silverick (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Front view (camera facing NW)



13 of 26

Photo taken by Don Silverick (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Exterior detail (west elevation)



4 of 26

Photo taken by Don Silverick (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Exterior detail (south elevation)



5 of 26

Photo taken by Don Silverek (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Front door (south elevation)



26 of 26

Photo taken by Don Silverak (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Front porch (camera facing east)



7 of 26

Photo taken by Don Silverek (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Reflecting pool / fountain (view from second floor room)



LY

#8 of 26

Photo taken by Don Silverick (1988)

Negatives at Sonoma County Architect, Sonoma County, CA

Staircase hall (camera facing north)



#1 of 16

Photo taken by Don Silverak (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Staircase hall / front door (camera facing south)



10 of 26

Photo taken by Don Silverick (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Staircase



11 of 26

Photo taken by Don Silverek (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Main dining room (camera facing NW)



12 of 26

Photo taken by Don Silverak (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Built-in hutch / buffet (main dining room)



Santa Rosa, Sonoma County, CA

#13 of 26

Photo taken by Don Silverek (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Wooden sconce/light fixture (main dining room)




14 of 26

Photo taken by Don Silverak (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Library (camera facing NW)



15 of 26

Photo taken by Don Silverek (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Library cabinetry



+ 16 of 26

Photo taken by Don Silverek (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Parlor / first floor (camera facing SE)



17 of 26

Photo taken by Don Silverek (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Upstairs bathroom (camera facing south)



16 of 26

Photo taken by Don Silverek (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Original dining room (camera facing NE)



10 of 26

Photo taken by Don Silverick (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Interior detail / library



17 of 26

Photo taken by Don Silverick (1988)

Negatives at Sonoma County Architect, Santa Rosa

Ceiling / library



21 of 26

Photo taken by Don Silverk (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Molding (front room / first floor)



55 of 26

Photo taken by Don Silverick (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Original: fireplace (front room / first floor)



11-20-20 of 26

Photo taken by Don Simunek (1978)

Negatives at Sonoma County Architect, Santa Rosa, CA

Original fireplace (original dining room)



24 of 26

Photo taken by Don Silverek (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Attic



Large House

San Francisco, California

1988 26

Photo taken by Don Silverick (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Attic



Hood House

26 of 26

Photo taken by Don Silverek (1988)

Negatives at Sonoma County Architect, Santa Rosa, CA

Foundation (field stone / timber)