

Schech's Mill

Vicinity of Sheldon, Minn.

Robert M. Frame III

1976

JAN 31 1978

Minnesota Historical Society, 690

Cedar Street, St. Paul, Minn.

Facing Southwest (Building's East
Elevation)

01719-8

AUG 29 1977

127

Houston Co



Schech's Mill

JAN 31 1978

Vicinity of Sheldon, Minn.

Robert M. Frame III

1976

AUG 29 1977


Minnesota Historical Society, 690

Cedar Street, St. Paul, Minn.

Interior, First Floor (View of
grinding floor and millstones

01718-2

2 @ 7 Houston Co.



Schech's Mill

Vicinity of Sheldon, Minn.

Robert M. Frame III
1976

JAN 31 1978


Minnesota Historical Society, 690
Cedar Street, St. Paul, Minn.

Interior of Second Floor, View of
Purifiers

01718-14

AUG 29 1977

3 of 7 Houston Co.



Schech's Mill

vicinity of Sheldon, Minnesota

Robert M. Frame III

1976

JAN 31 1978

Minnesota Historical Society, 690

Cedar Street, St. Paul, Minnesota

Hay barn and silo to southeast of

mill. Facing east

1/01719

4 of 7 Hanover Co.



Schech's Mill

vicinity of Sheldon, Minnesota

Robert M. Frame III

1976

JAN 31 1978

Minnesota Historical Society, 690

Cedar Street, St. Paul, Minn.

1896 swine barn complex to west of
mill. Facing north.

20A/01718

5 of 7 Houston Co.



Schech's Mill

Vicinity of Sheldon, Minnesota

Robert M. Frame III

1976

JAN 31 1978

Minnesota Historical Society, 690

Cedar Street, St. Paul, Minnesota

1922 concrete dam to southeast of
mill. Facing southeast

9/01719

697 Houston Co.



Schech's Mill

Vicinity of Sheldon, Minn.

Robert M. Frame III

1976

JAN 31 1978

Minnesota Historical Society, 690

Cedar Street, St. Paul, Minn.

Facing North (Building's south
elevation

01718-19

AUG 29 1977

797 Honaton Co.