


Santa Clara County WELCH-HURST H. WelchMAR-3t9 1978-car garage at rear of main house. Unique construction materials, Redwood pole and post frame. The wall panels are hand adzed Redwood planks. Photo taken late Fall 1976.



Santa Clara County

249

B. Welch-hurst. Photo taken easterly back down the driveway from the same spot as Photo A was taken westerly. Photo taken late Fall 1976. MAR 2 9 1978



Santa Clara County

C. <u>Welch-hurst</u>. Photo of the front of Welch-hurst main lodge showing some of the landscaping and part of the drive that circles the house. Large Madrone, Douglas Fir, and Redwood trees provide

the backdrop. Photo taken late Fall 1976.

MAR 2 5 1918 349

608 SEP 1 8 1978






D. <u>Welch-hurst</u>. Another photo of the front. The two tan sandstone slabs flanking the garden steps have a few Indian grinding holes (mortars). The stones appear to have been "quarried"

and turned vertical and set in place. Photo taken late Fall 1976.

DOE SEP 1 8 1978 MAR 2 9 1978 4079



Santa Clara County, Caif.


G. <u>Welch-hurst</u>. Picture taken from the front driveway showing stone steps and low wall around the Redwood Grove and barbeque area. Contemporary guest cottage roof shows in rear center of

photo. Photo taken late Fall 1976.

MAR 29 1978

549

DOC SEP 1 8 1978



Santa Clara County, California E. Welch-hurst. Close-up photo of southerly end of the main house showing the steps to the stone balustraded terrace. Photo taken late Fall 1976. MAR 2 9 1978 699 DOC

SEP 18 1978




Santa Clara County, California <u>Welch-hurst</u>. Photo taken across the south end the front the south of the front the F. from the south end the front showing part of the front garden and driveway. Part of the Redwood pergola on the front corner of the terrace is shown

on the left side of the photo. Photo taken late Fall 1976.

MAR 2 9 1978



1. <u>Welch-hurst</u>. Photo Raken near guest cottage (see photo G) across the driveway back to the Redwood Grove and barbeque area. Stone work both sides of 40/9drive. Photo taken late Fall 1976.





<u>Welch-hurst</u>. Photo of the driveway

Α. to Welch-hurst. Judge Welch had an existing natural pond on the right enlarged and landscaped. Photo taken late Fall 1976. MAR 2 9 1978

999

SEP 1 8 1978