



- 1) Charles Deering Estate
- 2) S.W. 167 St & Old Cutler Road, Dade County, Florida
- 3) Photographer: unknown
- 4) 1896

- 5) Historical Association of Southern Florida
- 6) S.H. Richmond's House at Cutler.
- 7) Photo no 1 of 61



- 1) Charles Deering Estate
- 2) S.W. 167 ST & Old Cutler Road, Dade County, FLA.
- 3) Photographer: unknown
- 4) After 1900 & before 1916
- 5) Historical Association of Southern Florida
- 6) Richmond Cottage at Cutler
- 7) Photo no 2 of 61



The Pier at the [illegible]

- 1) Charles Deering Estate
- 2) S.W. 167 ST. & Old Cutler Road, Dade County, FLA.
- 3) Photographer: unknown
- 4) 1902

- 5) Jean Taylor's Cutler Collection-Dade County Historic Preservation Division
- 6) From End of People's Dock Looking towards Richmond Cottage.

- 7) Photo no. 3 of 61.




- 1) Charles Deering Estate
- 2) S.w. 167 ST. & Old Cutler Road, Dade County, FLA.
- 3) Photographer: unknown
- 4) Circa 1904

- 5) Historical Association of Southern Florida
- 6) Richmond Cottage as shown in 1904, City of Miami Official Directory.
- 7) Photo No. 4 of 61



- 1) Charles Deering Estate
- 2) S.W. 167 ST. & Old Cutler Road, Dade County, FLA.
- 3) Photographer: unknown
- 4) Circa 1905

- 5) Jean Taylor's Cutler Collection-Dade County Historic Preservation Division
- 6) Frontal view of Richmond Cottage.
- 7) Photo no. 5 of 6!



- 1) Charles Deering Estate
- 2) S.W. 167 ST. & Old Cutler Road, Dade County, FLA.
- 3) Photographer - unknown
- 4) After 1900 before 1916


- 5) Jean Taylor's Cutler Collection, Dade County Historic Preservation Division
- 6) Side view of Richmond's House and Cottage.
- 7) Photo no. 6 of 61



- 1) Charles Deering Estate
- 2) S.W. 167 ST & Old Cutler Road, Dade County, FL
- 3) Photographer unknown
- 4) November 1916
- 5) Historical Association of Southern Florida
- 6) Richmond Cottage now owned by Charles Deering. Looking across the turning basin.
- 7) Photo No. 7 of 61



- 1) Charles Deering Estate
- 2) S.W. 167 ST & Old Cutler
Road, Dade County, FL
- 3) Photographer unknown
- 4) November 1916
- 5) Historical Association
of Southern Florida
- 6) Richmond Cottage, now owned
by Charles Deering
- 7) Photo No. 8 of 61



- 1) Charles Deering Estate
- 2) S.W. 167 ST & Old Cutler Road, Dade County, FL
- 3) Photographer unknown
- 4) Date unknown
- 5) Jean Taylor Cutler Collection, Dade County Historic Preservation Division
- 6) Charles Deering Home at Cutler, early photograph of the circa 1922 house
- 7) Photo No. 9 of 61



- 1) Charles Deering Estate
- 2) S.W. 167 ST & Old Cutler Road, Dade County, FL
- 3) Photographer: unknown
- 4) 1935
- 5) Historical Association of Southern Florida
- 6) Aerial view of Charles Deering Estate
- 7) Photo No. 10 of 61



1. Charles Deering Estate
- 2) S.w. 167 ST & Old Cutler Road, Dade County, FL
- 3) Ivan Rodriguez
- 4) Winter 1984
- 5) Dade County Historic

Preservation Division

- 6) Aerial view of Richmond Cottage & Charles Deering House
- 7) Photo No. 11 of 61



- 1) Charles Deering Estate
- 2) S.W. 167 ST & Old Cutler Road, Dade County, FL
- 3) Ivan Rodriguez
- 4) Winter 1984

- 5) Dade County Historic Preservation Division
- 6) Aerial view of Richmond Cottang & Charles Deering House
- 7) Photo No. 12 of 61



- 1) Charles Deering Estate
- 2) S.W. 167 ST & Old Cutler Road, Dade County, FL
- 3) Ivan Rodriguez
- 4) Winter 1984
- 5) Dade County Historic

Preservation Division

- 6) Aerial view of Lateral facades of Richmond Cottage & Charles Deering House
- 7) Photo No. 13 of 61



- 1) Charles Deering Estate
- 2) S.w. 167 ST & Old Cutler Road, Dade County, FL
- 3) Photographer unknown
- 4) Dade unknown
- 5) Dade County Historic Preservation Division
- 6) Front Arcade of Charles Deering House
- 7) Photo No. 14 of 61



- 1) Charles Deering Estate
- 2) S.W. 167 ST & Old Cutler
Road, Dade County, FL
- 3) Ivan Rodriguez
- 4) Winter 1984
- 5) Dade County Historic
Preservation Division
- 6) Front of the Deering Estate
- 7) Photo No. 15 of 61



- 1) Charles Deering Estate
- 2) S.W. 167 ST & Old Cutler
Road, Dade County, FL
- 3) Ivan Rodriguez
- 4) Winter 1984
- 5) Dade County Historic
Preservation Division
- 6) Aerial view of the Charles
Deering Estate
- 7) Photo No. 16 of 61



- 1) Charles Deering Estate
- 2) S.W. 167 ST & Old Cutler Road, Dade County, FL
- 3) Ivan Rodriguez
- 4) Winter 1984

- 5) Dade County Historic Preservation Division
- 6) Grounds of the Charles Deering Estate

- 7) Photo 17 of 61



F.C.M.
DE
SUP
2

- 1) Charles Deering Estate
- 2) S.W. 167 ST & Old Cutler Road, Dade County, FL
- 3) Photographer unknown
- 4) 1896

- 5) Jean Taylor Cutler Collection, Dade County Historic Preservation Division
- 6) Cutler Post Office

- 7) Photo 18 of 61



- 1) Charles Deering Estate
- 2) Cutler. Dade County, FL
- 3) Photographer unknown
- 4) Late 19th Century
- 5) Jean Taylor's Cutler
Collection. Dade County

Historic Preservation
Division

- 6) John Addison's home at
Cutler
- 7) Photo No. 19 of 61




Malt Mundy

Nelson Gorman

- 1) Charles Deering Estate
- 2) Old Cutler Village, Dade
County, FL
- 3) Photographer unknown
- 4) Late 19th Century
- 5) Jean Taylor's Cutler Col-
lection, Dade County

Historic Preservation
Division

- 6) Brown & Moody's store at
Cutler
- 7) Photo No. 20 of 61



1. Charles Deering Estate
- 2) Old Cutler Village. Dade County, FL
- 3) Photographer unknown
- 4) Late 19th Century
- 5) Jean Taylor's Cutler

- 6) Dougherty Factory & Home in Old Cutler Village
- 7) Photo No. 21 of 61



- 1) Charles Deering Estate
- 2) Corner of Mitchell & Old
Cutler Road, Dade County,
FL
- 3) Photographer unknown
- 4) Late 19th Century
- 5) Jean Taylor's Cutler
Collection. Dade County
Historic Preservation
- 6) Thomas & Sarah Mitchell at
their home on Mitchell &

Old Cutler Road

7) Photo No. 22 of 61



- 1) Charles Deering Estate
- 2) Cutler, Dade County, FL
- 3) Photographer unknown
- 4) Date unknown
- 5) Jean Taylor's Cutler
Collection. Dade County

- 6) The Fuzzard's dock at
Cutler
- 7) Photo No. 23 of 61



1. The Charles Deering Estate
2. South West 167 street and Old Cutler Road. Miami, Florida
3. Ivan Rodriguez
4. 1985
5. Dade County Historic Preservation Division
6. View of the Charles Deering Boat Basin
7. Photo no. 24 of 61



1. The Charles Deering Estate
2. South West 167 street and Old Cutler Road. Miami, Florida
3. Ivan Rodriguez
4. 1985
5. Dade County Historic Preservation Division
6. View of Charles Deering House and Richmond Cottage
7. Photo no. 25 of 61



1. The Charles Deering Estate
2. South West 167 street and Old Cutler Road. Miami, Florida
3. Ivan Rodriguez
4. 1985
5. Dade County Historic Preservation Division
6. Front view of the Charles Deering House
7. Photo no. 26 of 61



1. The Charles Deering Estate
2. South West 167 street and Old Cutler Road. Miami, Florida
3. Ivan Rodriguez
4. 1985
5. Dade County Historic Preservation Division
6. Detail of the Front Colonade of the Charles Deering House Breezeway
7. Photo no. 27 of 61



1. The Charles Deering Estate
2. South West 167 street and Old Cutler Road. Miami, Florida
3. Ivan Rodriguez
4. 1985
5. Dade County Historic Preservation Division
6. Side view of the Charles Deering House
7. Photo no. 28 of 61



1. The Charles Deering Estate
2. South West 167 street and Old Cutler Road. Miami, Florida
3. Ivan Rodriguez
4. 1985
5. Dade County Historic Preservation Division
6. Rear facade and breezeway of the Charles Deering House
7. Photo no. 29 of 61



1. The Charles Deering Estate
2. South West 167 street and Old Cutler Road. Miami, Florida
3. Ivan Rodriguez
4. 1985
5. Dade County Historic Preservation Division
6. Detail of the rear breezeway of the Charles Deering House
7. Photo no. 30 of 61



1. The Charles Deering Estate
2. South West 167 street and Old Cutler Road. Miami, Florida
3. Ivan Rodriguez
4. 1985
5. Dade County Historic Preservation Division
6. Adjacent breezeways of the Charles Deering House and the Richmond Cottage
7. Photo no. 31 of 61



1. The Charles Deering Estate
2. South West 167 street and Old Cutler Road. Miami, Florida
3. Ivan Rodriguez
4. 1985
5. Dade County Historic Preservation Division
6. Front of the Richmond Cottage
7. Photo no. 32 of 61



1. The Charles Deering Estate
2. South West 167 street and Old Cutler Road. Miami, Florida
3. Ivan Rodriguez
4. 1985
5. Dade County Historic Preservation Division
6. Aerial view of the Richmond Cottage
7. Photo no. ~~33~~ of 61




1. The Charles Deering Estate
2. South West 167 street and Old Cutler Road. Miami, Florida
3. Ivan Rodriguez
4. 1985
5. Dade County Historic Preservation Division
6. Side view of the Richmond Cottage
7. Photo no. ~~34~~ of 61




1. The Charles Deering Estate
2. South West 167 street and Old Cutler Road. Miami, Florida
3. Ivan Rodriguez
4. 1985
5. Dade County Historic Preservation Division
6. Side view of the Richmond House
7. Photo no. 35 of 61



1. The Charles Deering Estate
2. South West 167 street and Old Cutler Road. Miami, Florida
3. Ivan Rodriguez
4. 1985
5. Dade County Historic Preservation Division
6. Cutler Ridge Mound
7. Photo no. 36 of 61



1. The Charles Deering Estate
Wall and a portion of Old
Cutler Road
2. S.W. 167 Street and Old
Cutler Road
3. Elise Brault-Hoessly
4. March 1985
5. Dade County Historic
Preservation Division
6. Entrance gate to Deering
Estate Housing Compound
7. Photo No. 37 of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Elise Brault-Hoessly
4. March, 1985
5. Dade County Historic Preservation Division
6. View of the oolitic limestone wall of the Charles Deering Estate
7. Photo No. 38 of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Elise Brault-Hoessly
4. March, 1985
5. Dade County Historic Preservation Division
6. Detail of oolitic limestone rock column
7. Photo No. 39 of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Elise Brault-Hoessly
4. March, 1985
5. Dade County Historic Preservation Division
6. Concrete and arched shaped bridge on Ingraham Highway
7. Photo No. 40 of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Department
6. Main staircase and vaulted ceiling in Deering House
7. Photo No. 41 of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Department
6. Deering House ballroom
7. Photo No. 42 of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Department
6. Deering House ballroom
7. Photo No. 43 of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Department
6. Deering House ballroom, fireplace detail
7. Photo No. 44 of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Department
6. Deering House ballroom, ceiling detail
7. Photo No. 45 of 61



1. The Charles Deering Estate
2. SW 167th Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Department
6. Deering House wrought iron gate from ballroom to central hall
7. Photo No. 46 of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Department
6. Deering House library and fireplace detail
7. Photo No. 47 of 61




1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Department
6. Deering House staircase detail
7. Photo No. 48 of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Department
6. Deering House second story bedroom and fireplace detail
7. Photo No. 49 of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Division
6. Deering House bathroom
7. Photo No. 50 of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Division
6. Deering House light fixture detail
7. Photo No. ~~51~~ of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Division
6. Richmond House pantry
7. Photo 52 of 61




1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Division
6. Richmond House kitchen
7. Photo No. 53 of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Division
6. Richmond House kitchen
7. Photo No. 54 of 61



1. The Charles Deering EState
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Division
6. Richmond House Dining Room and fireplace detail
7. Photo No. 55 of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Division
6. Richmond House dining room
7. Photo No. 56 of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Division
6. room connecting Richmond House to Richmond Cottage
7. Photo No. 57 of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Division
6. Room connecting Richmond House to Richmond Cottage
7. Photo No. 58 of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Division
6. Richmond Cottage, ground floor, north
7. Photo No. 59 of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Division
6. Richmond Cottage, staircase detail
7. Photo No. 60 of 61



1. The Charles Deering Estate
2. SW 167 Street and Old Cutler Road
3. Richard Johnson
4. October, 1985
5. Dade County Historic Preservation Division
6. Richmond Cottage, staircase detail
7. Photo No. 61 of 61