



#4

Cross Manor

St. Mary's County, Md.

Photographer: Robert J. Hughes

June, 1987

Negative: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

View From east

1 of 23



#2

Cross Manor

St. Mary's County, Md.

Photographer: Robert J. Hughes

June, 1987

Negative: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

View from north

2 of 23



#3

Cross Manor

St. Mary's County, Md.

Photographer: Robert J. Hughes

June, 1987

Negative: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

View from south

3 of 23



#1

Cross Manor, SM-3

St. Mary's County, Md.

Photographer: Robert J. Hughes

June, 1987

Negative: Robert J. Hughes, 148 12th St, SE, Wash., DC 20003

View from west

4 of 23



#5

Cross Manor

St. Mary's County, Md.


Photographer: Robert J. Hughes

April, 1987

Negative: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

Carriage House, east side

5 of 23



#6

Cross Manor

St. Mary's County, Md.

Photographer: Robert J. Hughes

February, 1988

Negative: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

Corn Crib

6 of 23



#7

Cross Manor

St. Mary's County, Md.

Photographer: Robert J. Hughes

February, 1988

Negative: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

Barn, west end

7 of 23



#8

Cross Manor

St. Mary's County, Md.

Photographer: Robert J. Hughes

February, 1988

Negative: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

Barn, south side

8 of 23



#9

Cross Manor

St. Mary's County, Md.

Photographer: Robert J. Hughes

September, 1987

Negative: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

Sheep Shed

9 of 23



#10

Cross Manor

St. Mary's County, Md.

Photographer: Robert J. Hughes

June, 1987

Negative: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

Free-standing chimney

10 of 23



Cross Manor

St. Mary's County, Md.

Photographer: Robert J. Hughes

June, 1987

Negative: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

Corner of foundation of demolished building at free-standing chimney

11 of 23



Cross Manor

St. Mary's County, Md.

Photographer: Robert J. Hughes

December, 1987

Neg: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

North wall excavation

12 of 23.



Cross Manor

St. Mary's County, Md.

Photographer: Robert J. Hughes

February, 1988

Neg: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

Brick walk under porch on west side of kitchen wing

13 of 23



Cross Manor

St. Mary's County, Md.

Photographer: Robert J. Hughes

October, 1987

Neg: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

Center fireplace inside kitchen wing with root cellar at Foot

14 of 23



Cross Manor

St. Mary's County, Md.

Photographer: Robert J. Hughes

December, 1987

Neg: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

Detail of root cellar in kitchen wing

15 of 23

Cross Manor
Kitchen
Unit 6
Feature
2/4/88



Cross Manor

St. Mary's County, Md.

Photographer: Robert Veery

February, 1988

Neg: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

Excavation in passageway between kitchen & main house

16 of 23



Cross Manor

St. Mary's County, Md.

Photographer: Robert Veery

February, 1988

Neg: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

Excavation in passageway between kitchen & main house

17 of 23

A black and white photograph of an archaeological excavation site. In the foreground, a small chalkboard is propped up against a dirt wall. The chalkboard has handwritten text in white chalk. To the left of the chalkboard, a trowel is visible. To the right, a measuring tape is extended. The background shows a large, roughly rectangular feature in the earth, possibly a foundation or a pit, with some faint markings on its surface. The overall scene is dimly lit, suggesting an indoor or shaded excavation environment.

Cross Manor
Kitchen
Units 10+27
Feature--base
1/6/88

Cross Manor

St. Mary's County, Md.

Photographer: Robert Veery

February, 1988

Neg: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

Excavation - original ~~Foundation~~ line of kitchen

18 of 23



Cross Manor

St. Maru's County, Md.

Photographer: Robert J. Hughes

April, 1987

Neg: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

First Floor hallway, east to west

19 of 23



Cross Manor

St. Mary's County, Md.

Photographer: Robert J. Hughes

June, 1987

Neg: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

First Floor, west parlor

20 of 23



Cross Manor

St. Mary's County, Md.

Photographer: Robert J. Hughes

June, 1987

Neg: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

2nd Floor, east room

21 of 23



Cross Manor

St. Mary's County, Md.

Photographer: Robert J. Hughes

June, 1987

Neg: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

2nd Floor, west room, mantel

22 of 23



Cross Manor

St. Mary's County, Md.

photographer: Robert J. Hughes

October, 1987

Neg: Robert J. Hughes, 148 12th St., SE, Wash., DC 20003

Left over kitchen wing

23 of 23