



Benedict Miller House

32 Hillside Ave., Waterbury, Conn.

Photo: Ann Smith, January 1979

Negative: Mattatuck Historical
Society

Photo 1: Facade

APR 30 1981

View: North

New Haven Co.



32 Hillside Ave., *Benedict Miller House*
Waterbury, Conn.

Photo: Ann Smith, January 1979

Negative: Mattatuck Historical
Society

Photo 2: 32 Hillside Ave., Classroom
Building, Palliser house
built for Benedict's sister

View: Northwest *New Haven Ctr.*



Benedict - Miller Home

32 Hillside Ave., Waterbury, Conn.

Photo: Ann Smith, January 1979

Negative: Mattatuck Historical
Society

Photo 3: 70 Hillside Ave., 86
Hillside Ave.

View: North *New Haven Co.*



Benedict-Miller House
32 Hillside Ave., Waterbury, Conn.


Photo: Ann Smith, January 1979

Negative: Mattatuck Historical
Society

Photo 4: Facade, 32 Hillside Ave.

View: Northeast

JUN 12 1981 *New Haven Co.* APR 30 1981



Benedict-Miller House

32 Hillside Ave., Waterbury, Conn.

Photo: Ann Smith, January 1979

Negative: Mattatuck Historical
Society

Photo 5: Southeast elevation and
servants wing

View: Northwest

New Haven Co

JUN 12 1981



Benedict Miller Home

32 Hillside Ave., Waterbury, Conn.

Photo: Ann Smith, January 1979

Negative: Mattatuck Historical
Society

Photo 6; North and east elevations

View: Southwest

APR 30 1981

JUN 12 1981

New Haven Co.

F
1886



Benedict Miller House
32 Hillside., Waterbury, Conn.

Photo: Ann Smith, January 1979

Negative: Mattatuck Historical
Society

Photo 7: North and west elevations

View: Southeast

New Haven Co.



Benedict-Miller House
32 Hillside Ave., Waterbury, Conn.

Photo: Ann Smith, January 1979

Negative: Mattatuck Historical
Society

Photo 8: Main bay, southwest corner
of house and profile of
facade and verandah

View: East *New Haven Co.*



Benedict - Miller House
32 Hillside Ave., Waterbury, Conn.

Photo: Ann Smith, January 1979

Negative: Mattatuck Historical
Society

Photo 9: Detail, brownstone stairs
to verandah

View: West *New Haven Co.*



Benedict Miller House

32 Hillside Ave., Waterbury, Conn.

Photo: Ann Smith, January 1979

Negative: Mattatuck Historical
Society *New Haven Co.*

Photo 10: Detail: Carving on
interior stairway

View: East