



Name: "Glynrich"; Richard Richardson House
(N-360) left; Brick Mill House (N-361) right
Location: Vicinity of Richardson Park, New Castle C, Del.

Photographer: unknown

Date: c. 1887-1888

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: an early photograph depicting the dwellings.

Courtesy of the Historical Society of Delaware

Photograph Number: 1 of 25

DOE
NOV 1 1979

80 AUG 1979



Name: Glynrich: The Richard Richardson House

Location: Vicinity of Richardson Park, New Castle County,
Delaware

Photographer: Richard T. Jett

Date: June, 1979


Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Facade of five-bay main block and service
wing showing dormers added in 1929 and the Georgian
Revival porch added about 1900.

Photograph Number: 2 of
25

DDK
NOV 1 1979

80 AUG 1979



Name: Glynrich: The Richard Richardson House

Location: Vicinity of Richardson Park, New Castle County,
Delaware

Photographer: Richard T. Jett

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901


Description: Rear elevation of main block

Photograph Number:

3 of
25

NOV 1 ^{DOE} 1979

80 AUG 1979



Name: Glynrich: The Richard Richardson House

Location: Vicinity of Richardson Park, New Castle County,
Delaware

Photographer: Richard T. Jett

Date: June 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: End wall of main block seen from southwest
showing modillion cornice, six-light gable window,
chimney and dormers.

Photograph Number: 4 of
25

NOV 1 ^{DOE} 1979

30 AUG 1979



Name: Glynrich: The Richard Richardson House

Location: Vicinity of Richardson Park, New Castle County,
Delaware

Photographer: Richard T. Jett

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Detail of end wall showing datestone and
modillion cornice.

Photograph Number:

5 of
25

DOE
NOV 1 1979

30 AUG 1979



Name: **Glynrich:** The Richard Richardson House

Location: Vicinity of Richardson Park, New Castle County,
Delaware

Photographer: Richard T. Jett

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Facade entrance, including five-light transom
doorway and central pediment of five-bay Georgian Revival
porch.

Photograph Number: 6 of

25

NOV 1 1979

DOE
30 AUG 1979



Name: Glynrich: The Richard Richardson House

Location: Vicinity of Richardson Park, New Castle County,
Delaware 19901

Photographer: Richard T. Jett

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: First floor facade window showing raised panel
shutters and hardware.

Photograph Number:

7 of
25

DOE
NOV 1 1979

30 AUG 1979



Name: Glynrich: The Richard Richardson House

Location: Vicinity of Richardson Park, New Castle County,
Delaware 19901

Photographer: Richard T. Jett

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: First floor rear window with raised panel
shutters.

Photograph Number: 8 of
25

DOE

NOV 1 1979

80 AUG 1979



Name: Glynrich: The Richard Richardson House

Location: Vicinity of Richardson Park, New Castle County,

Delaware
Photographer: Richard T. Jett

Date: June , 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Detail of rear window hardware

Photograph Number: 9 of
25

DOE
NOV 1 1979

30 AUG 1979



Name: Richard Richardson House (N-360)

Location: Vicinity of Richardson Park, New Castle County, DE

Photographer: Richard Jett

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description:stairhall.

Photograph Number:

10 of
25

NOV 1 ^{DOE} 1979

30 AUG 1979



Name: Richard Richardson House (N-360)

Location: Vicinity of Richardson Park, New Castle County, DE

Photographer: Richard Jett

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: staircase detail.

Photograph Number: 11 of
25

DOE
NOV 1 1979

80 AUG 1979



Name: Richard Richardson House (N-360)

Location: Vicinity of Richardson Park, New Castle County, DE

Photographer: Richard Jett

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: chimney breast panelling; southwest room of the
first floor.

Photograph Number:

12 of
25

DOE
NOV 1 1979

80 AUG 1979



Name: Richard Richardson House(N-360)

Location: Vicinity of Richardson Park, New Castle County, DE

Photographer: Richard Jett

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: chimney breast panelling; northeast room of the
first floor.

Photograph Number:

13 of
25

DOE
NOV 1 1979

30 AUG 1979



Name: Richard Richardson House (N-360)

Location: Vicinity of Richardson Park, New Castle County,
DE

Photographer: Richard Jett

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: doorway on panelled fireplace wall, north-
east room of the first floor.

Photograph Number: 14 of
25

00e
NOV 1 1979

80 AUG 1979



Name: Richard Richardson House (N-360)

Location: Vicinity of Richardson Park, New Castle County,
Delaware

Photographer: Richard Jett

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: cornice detail; first floor.

Photograph Number:

15 of
25

DOE
NOV 1 1979

30 AUG 1979



Name: Richard Richardson House (N-360)

Location: Vicinity of Richardson Park, New Castle County, DE

Photographer: Richard Jett

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: doorway detail; southwest room of the first
floor.

Photograph Number:

16 of
25

DOE
NOV 1 1979

30 AUG 1979



Name: Richard Richardson House (N-360)

Location: Vicinity of Richardson Park, New Castle County,

DE

Photographer: Richard Jett

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,

B/A&HP, Hall of Records, Dover, Delaware 19901

Description: window detail; southwest room of the first floor.

Photograph Number:

17 of
25

DOE
NOV 1 1979

30 AUG 1979



Name: Glynrich: The Brick Mill House (N-361)

Location Vicinity of Richardson Park, New Castle County,

Photographer: ^{Del.} Richard T. Jett

Date: June 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Rear and side elevations showing modern
kitchen addition.

Photograph Number: 18 of 25

NOV 1 ^{DE} 1979

30 AUG 1979



Name: Glynrich: The Brick Mill House (N-361)

Location: Vicinity of Richardson Park, New Castle County,

Photographer: ^{Del.} Richard T. Jett

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Stuccoed end wall taken from the South showing
belt course, attic window, "musket window", the lean-to
addition and the raised basement.

Photograph Number: 19 of 25

NOV 1 ^{DOE} 1979

30 AUG 1979



Name: Glynrich: The Brick Mill House (N-361)

Location: Vicinity of Richardson Park, New Castle, County,
Del.

Photographer: Richard T. Jett

Date: June 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Portion of the facade to the left of the main
entrance showing notable features of the masonry con-
struction including Flemish bond brick work, segmental
arch over the first floor window and abbreviated belt
course over entrance porch.

Photograph Number: 20 of

25

NOV 1 1979

30 AUG 1979



Name: Glynrich: The Brick Mill House

Location: Vicinity of Richardson Park, New Castle County,
Delaware

Photographer: Richard T. Jett

Date: June 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Detail of facade showing Flemish bond brick-
work and segmental arch over window to the left of the
entrance, as well as the modern board and batten shutters
added in the 1950's.

Photograph Number:

21 of
25

DOE
NOV 1 1979

30 AUG 1979



Name: Glynrich: The Brick Mill House (N-361)

Location: Vicinity of Richardson Park, New Castle County,
Delaware

Photographer: Richard T. Jett

Date: June, 1979


Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: Facade entrance including four-lite transom
doorway, six-panel door and portions of the porch.

Photograph Number: 22 of
25

DOE
NOV 1 1979

30 AUG 1979



Name: Brick Mill House(N-361)

Location: Vicinity of Richardson Park, New Castle County, DE

Photographer: Richard Jett

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: hall chimney breast and mantel shelf

Photograph Number:

23 of
25

DOE
NOV 1 1979

30 AUG 1979



Name: Brick Mill House (N-361)

Location: Vicinity of Richardson Park, New Castle County, DE

Photographer: Richard Jett

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs,

B/A&HP, Hall of Records, Dover, Delaware 19901

Description: mantel shelf, parlor chamber

Photograph Number:

24 of
25

DOE
NOV 1 1979

30 AUG 1979



Name: Brick Mill House (N-361)

Location: Vicinity of Richardson Park, New Castle County, DE

Photographer: Richard Jett

Date: June, 1979

Location of Negative: Div. of Historical & Cultural Affairs
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: closet door, left of fireplace in parlor chamber

Photograph Number:

25 of
25

DOE
NOV 1 1979

30 AUG 1979