

St. Michael's Catholic Church Complex (GY06-1)

Photo by Joni Gilkerson, Nebraska State Historical Society May, 1983 (8305/3:25)

Spalding, Greeley County, Nebraska

Photo #13 of 14

View looking northwest showing south and east facades of the parish center.



Photo #14 of 14

St. Michael's Catholic Church Complex (GY06-1)

Spalding, Greeley County, Nebraska
Photo by Joni Gilkerson, Nebraska
State Historical Society
May, 1983 (8305/3:19)

View looking northwest showing south and east facades of rectory.



St. Michael's Catholic Church Complex (GY06-1)

Photo #1 of 14

Spalding, Greeley County, Nebraska
Photo by Joni Gilkerson, Nebraska

May, 1983 (8305/4:15)

General view looking northeast showing church, academy and convent.

State Historical Society



Photo #2 of 14

St. Michael's Catholic Church Complex (GY06-1)

Spalding, Greeley County, Nebraska

Photo by Joni Gilkerson, Nebraska
State Historical Society

May, 1983 (8305/4:33)

View looking northeast showing south and west facades of church.




Photo #3 of 14

St. Michael's Catholic Church Complex (GY06-1)
Spalding, Greeley County, Nebraska

Photo by Joni Gilkerson, Nebraska State Historical Society May, 1983 (8305/4:26)

View looking east northeast showing west and south facades of church.



Photo #4 of 14

St. Michael's Catholic Church Complex (GY06-1)
Spalding, Greeley County, Nebraska

Photo by Joni Gilkerson, Nebraska State Historical Society May, 1983 (8305/3:28)

View looking southeast showing north and west facades of church.




Photo #5 of 14

St. Michael's Catholic Church Complex (GY06-1)
Spalding, Greeley County, Nebraska

Photo by Joni Gilkerson, Nebraska State Historical Society May, 1983 (8305/3:22)

View looking north showing detail of south (front) entry.



Photo #6 of 14

St. Michael's Catholic Church Complex

(GY06-1)
Spalding, Greeley County, Nebraska

Photo by Joni Gilkerson, Nebraska State Historical Society May, 1983 (8305/9:10)

Interior view of church looking north from the nave toward the chancel area.



St. Michael's Catholic Church Complex

(GY06-1)
Spalding, Greeley County, Nebraska

Photo by Joni Gilkerson, Nebraska State Historical Society May, 1983 (8305/9:2)

Photo #7 of 14

Interior view of church looking north showing the sanctuary.



St. Michael's Catholic Church Complex

Photo #8 of 14

(GY06-1) Spalding, Greeley County, Nebraska

Photo by Joni Gilkerson, Nebraska State Historical Society May, 1983 (8305/9:24)

Interior view of church looking northeast showing transept area.




St. Michael's Catholic Church Complex (GY06-1)

Spalding, Greeley County, Nebraska

Photo #9 of 14

Photo by Joni Gilkerson, Nebraska State Historical Society May, 1983 (8305/9:8)

Interior view of church looking south from the nave toward the balcony area.



St. Michael's Catholic Church Complex

Photo #10 of 14

(GY06-1) Spalding, Greeley County, Nebraska

Photo by Joni Gilkerson, Nebraska State Historical Society May, 1983 (8305/9:17)

Interior view of church looking south from the balcony showing detail of window.



Photo #11 of 14

St. Michael's Catholic Church Complex (GY06-1)

Photo by Joni Gilkerson, Nebraska State Historical Society May, 1983 (8305/4:13)

Spalding, Greeley County, Nebraska

General view looking northeast showing south and west facades of the convent and academy.




Photo #12 of 14

St. Michael's Catholic Church Complex (GY06-1)

Spalding, Greeley County, Nebraska

Photo by Joni Gilkerson, Nebraska
State Historical Society
May, 1983 (8305/4:8)

May, 1983 (8305/4:8)
View looking north showing south (front)

facade of the academy.